

GSP AUTO PARTS

DRIVELINE COMPONENTS NEW DEVELOPED JULY 2020



MANUFACTURER	MODEL	DISPLACEMENT	YEAR	REMARK	FITTING POSITION	PRODUCT	GSP NO.
AUDI	A3 (8P1)	2.0 TDI 16V quattro (103 kw)	2004.08-2012.08	Rear	AWD Engine BKD, CBAB, CFFB	Joint,Propeller Shaft	533882
AUDI	A3 (8P1)	2.0 TDI 16V quattro (103 kw)	2004.08-2012.08	Front	AWD Engine BKD, CBAB, CFFB	Joint,Propeller Shaft	537626
AUDI	A3 (8P1)	2.0 TDI quattro (100 kw)	2003.05-2008.06	Rear	AWD Engine AZV	Joint,Propeller Shaft	533882
AUDI	A3 (8P1)	2.0 TDI quattro (100 kw)	2003.05-2008.06	Front	AWD Engine AZV	Joint,Propeller Shaft	537626
AUDI	A3 (8P1)	2.0 TDI quattro (103 kw)	2006.01-2008.06	Rear	AWD Engine BMM	Joint,Propeller Shaft	533882
AUDI	A3 (8P1)	2.0 TDI quattro (125 kw)	2006.03-2012.08	Rear	AWD Engine BMN, CBBB, CFCB	Joint,Propeller Shaft	533882
AUDI	A3 (8P1)	2.0 TDI quattro (125 kw)	2006.03-2012.08	Front	AWD Engine BMN, CBBB, CFCB	Joint,Propeller Shaft	537626
AUDI	A3 (8P1)	2.0 TFSI quattro (147 kw)	2004.09-2012.08	Rear	AWD Engine AXV, BWA, CCZA	Joint,Propeller Shaft	533882
AUDI	A3 (8P1)	2.0 TFSI quattro (147 kw)	2004.09-2012.08	Front	AWD Engine AXV, BWA, CCZA	Joint,Propeller Shaft	537626
AUDI	A3 (8P1)	3.2 V6 quattro (184 kw)	2003.07-2009.05	Rear	AWD Engine BDB (07.03-), BMJ (09.04-), BUB	Joint,Propeller Shaft	533882
AUDI	A3 (8P1)	3.2 V6 quattro (184 kw)	2003.07-2009.05	Front	AWD Engine BDB (07.03-), BMJ (09.04-), BUB	Joint,Propeller Shaft	537626
AUDI	A3 (8P1)	S3 quattro (188 kw)	2007.02-2012.08	Front	AWD Engine BZC, CDLC	Joint,Propeller Shaft	537626
AUDI	A3 (8P1)	S3 quattro (195 kw)	2006.11-2012.08	Rear	AWD Engine BHZ, CDLA	Joint,Propeller Shaft	533882
AUDI	A3 (8P1)	S3 quattro (195 kw)	2006.11-2012.08	Front	AWD Engine BHZ, CDLA	Joint,Propeller Shaft	537626
AUDI	A3 Sportback (8PA)	2.0 TDI 16V quattro (103 kw)	2005.11-2013.03	Rear	AWD Engine BKD, CBAB, CFFB	Joint,Propeller Shaft	533882
AUDI	A3 Sportback (8PA)	2.0 TDI 16V quattro (103 kw)	2005.11-2013.03	Front	AWD Engine BKD, CBAB, CFFB	Joint,Propeller Shaft	537626
AUDI	A3 Sportback (8PA)	2.0 TDI quattro (103 kw)	2006.01-2008.06	Rear	AWD Engine BMM	Joint,Propeller Shaft	533882
AUDI	A3 Sportback (8PA)	2.0 TDI quattro (103 kw)	2006.01-2008.06	Front	AWD Engine BMM	Joint,Propeller Shaft	537626
AUDI	A3 Sportback (8PA)	2.0 TDI quattro (125 kw)	2006.03-2013.03	Rear	AWD Engine BMN, CBBB, CFCB	Joint,Propeller Shaft	533882
AUDI	A3 Sportback (8PA)	2.0 TDI quattro (125 kw)	2006.03-2013.03	Front	AWD Engine BMN, CBBB, CFCB	Joint,Propeller Shaft	537626
AUDI	A3 Sportback (8PA)	2.0 TFSI quattro (147 kw)	2004.09-2013.03	Rear	AWD Engine AXV (09.04-), BPF, BWA, CBA, CCA, CCZA	Joint,Propeller Shaft	533882
AUDI	A3 Sportback (8PA)	2.0 TFSI quattro (147 kw)	2004.09-2013.03	Front	AWD Engine AXV (09.04-), BPF, BWA, CBA, CCA, CCZA	Joint,Propeller Shaft	537626
AUDI	A3 Sportback (8PA)	3.2 V6 quattro (184 kw)	2004.09-2009.05	Rear	AWD Engine BDB, BMJ (09.04-), BUB	Joint,Propeller Shaft	533882
AUDI	A3 Sportback (8PA)	3.2 V6 quattro (184 kw)	2004.09-2009.05	Front	AWD Engine BDB, BMJ (09.04-), BUB	Joint,Propeller Shaft	537626
AUDI	Q3 (8UB, 8UG)	2.0 TDI quattro (103 kw)	2012.01-2018.10	Rear	AWD Engine CFFB	Joint,Propeller Shaft	533882
AUDI	Q3 (8UB, 8UG)	2.0 TDI quattro (110 kw)	2014.11-2018.10	Rear	AWD Engine CUVC, DFTA	Joint,Propeller Shaft	533882
AUDI	Q3 (8UB, 8UG)	2.0 TDI quattro (120 kw)	2011.06-2015.04	Rear	AWD Engine CFGD	Joint,Propeller Shaft	533882
AUDI	Q3 (8UB, 8UG)	2.0 TDI quattro (130 kw)	2011.06-2018.10	Rear	AWD Engine CFGC, CLLB	Joint,Propeller Shaft	533882
AUDI	Q3 (8UB, 8UG)	2.0 TDI quattro (135 kw)	2014.11-2018.10	Rear	AWD Engine CUWA, CYLA, DFUA	Joint,Propeller Shaft	533882
AUDI	Q3 (8UB, 8UG)	2.0 TFSI quattro (125 kw)	2011.06-2015.04	Rear	AWD Engine CCZC	Joint,Propeller Shaft	533882
AUDI	Q3 (8UB, 8UG)	2.0 TFSI quattro (132 kw)	2014.11-2018.10	Rear	AWD Engine CULB	Joint,Propeller Shaft	533882
AUDI	Q3 (8UB, 8UG)	2.0 TFSI quattro (147 kw)	2014.09-2018.10	Rear	AWD Engine CCTA	Joint,Propeller Shaft	533882
AUDI	Q3 (8UB, 8UG)	2.0 TFSI quattro (155 kw)	2011.06-2015.04	Rear	AWD Engine CPXA	Joint,Propeller Shaft	533882
AUDI	Q3 (8UB, 8UG)	2.0 TFSI quattro (162 kw)	2014.11-2018.10	Rear	AWD Engine CULC	Joint,Propeller Shaft	533882
AUDI	TT (8N3)	1.8 T quattro (132 kw)	1998.10-2006.06	Front	AWD Engine AJQ, ARY, ATC, AUQ	Joint,Propeller Shaft	537626
AUDI	TT (8N3)	1.8 T quattro (140 kw)	2005.09-2006.06	Front	AWD Engine BVR	Joint,Propeller Shaft	537626
AUDI	TT (8N3)	1.8 T quattro (165 kw)	1998.10-2006.06	Front	AWD Engine APX, BAM, BEA	Joint,Propeller Shaft	537626
AUDI	TT (8N3)	1.8 T quattro (180 kw)	2005.03-2006.06	Front	AWD Engine BFV	Joint,Propeller Shaft	537626
AUDI	TT (8N3)	3.2 VR6 quattro (184 kw)	2003.07-2006.06	Front	AWD Engine BHE (07.03-), BPF	Joint,Propeller Shaft	537626
AUDI	TT Roadster (8N9)	1.8 T quattro (132 kw)	2000.02-2006.06	Front	AWD Engine AJQ, ARY, AUQ	Joint,Propeller Shaft	537626
AUDI	TT Roadster (8N9)	1.8 T quattro (140 kw)	2005.09-2006.06	Front	AWD Engine BVR	Joint,Propeller Shaft	537626
AUDI	TT Roadster (8N9)	1.8 T quattro (165 kw)	1999.10-2006.06	Front	AWD Engine APX, BAM, BEA	Joint,Propeller Shaft	537626
AUDI	TT Roadster (8N9)	3.2 VR6 quattro (184 kw)	2003.07-2006.06	Front	AWD Engine BHE (07.03-), BPF	Joint,Propeller Shaft	537626
BMW	1 (F20)	114 d (70 kw)	2012.11-2015.06	Rear	Engine N47 D16 A	Joint,Propeller Shaft	537625
BMW	1 (F20)	114 i (75 kw)	2012.07-2015.02	Rear	Engine N13 B16 A	Joint,Propeller Shaft	537625
BMW	1 (F20)	116 d (85 kw)	2011.07-2015.02	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	1 (F20)	116 d (85 kw)	2012.03-2015.02	Rear	Engine N47 D16 A	Joint,Propeller Shaft	537625
BMW	1 (F20)	116 i (100 kw)	2011.07-2015.02	Rear	Engine N13 B16 A	Joint,Propeller Shaft	537625
BMW	1 (F20)	116 i (80 kw)	2015.03-2019.06	Rear	Engine B38 B15 A	Joint,Propeller Shaft	537625
BMW	1 (F20)	118 d (100 kw)	2011.07-2019.06	Rear	Engine B47 D20 A (03.15-), N47 D20 C (-02.15)	Joint,Propeller Shaft	537625
BMW	1 (F20)	118 d (105 kw)	2011.07-2015.02	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	1 (F20)	118 d (110 kw)	2015.03-2019.06	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	1 (F20)	118 d xDrive (110 kw)	2015.03-2019.06	Rear	AWD Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	1 (F20)	118 i (100 kw)	2015.03-2015.06	Rear	Engine N13 B16 A	Joint,Propeller Shaft	537625
BMW	1 (F20)	118 i (100 kw)	2015.07-2019.06	Rear	Engine B38 B15 A	Joint,Propeller Shaft	537625
BMW	1 (F20)	118 i (125 kw)	2011.07-2015.02	Rear	Engine N13 B16 A	Joint,Propeller Shaft	537625
BMW	1 (F20)	120 d (120 kw)	2011.07-2019.06	Rear	Engine B47 D20 A, N47 D20 C	Joint,Propeller Shaft	537625
BMW	1 (F20)	120 d (135 kw)	2011.07-2015.02	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	1 (F20)	120 d (140 kw)	2015.03-2019.06	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	1 (F20)	120 d (147 kw)	2011.07-2015.02	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	1 (F20)	120 d xDrive (135 kw)	2012.11-2015.02	Rear	AWD Engine N47 D20 C	Joint,Propeller Shaft	537625

MANUFACTURER	MODEL	DISPLACEMENT	YEAR	REMARK	FITTING POSITION	PRODUCT	GSP NO.
BMW	1 (F20)	120 d xDrive (140 kw)	2015.03-2019.06	Rear	AWD Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	1 (F20)	120 d xDrive (147 kw)	2012.11-2015.02	Rear	AWD Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	1 (F20)	120 i (130 kw)	2015.03-2016.06	Rear	Engine N13 B16 A	Joint,Propeller Shaft	537625
BMW	1 (F20)	120 i (135 kw)	2016.07-2019.06	Rear	Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	1 (F20)	125 d (160 kw)	2012.03-2015.02	Rear	Engine N47 D20 D	Joint,Propeller Shaft	537631
BMW	1 (F20)	125 i (160 kw)	2012.03-2017.11	Rear	Engine N20 B20 A	Joint,Propeller Shaft	537625
BMW	1 (F20)	125 i (165 kw)	2016.07-2019.06	Rear	Engine B48 B20 B	Joint,Propeller Shaft	537625
BMW	1 (F20)	125 i (175 kw)	2012.03-2017.11	Rear	Engine N20 B20 A	Joint,Propeller Shaft	537625
BMW	1 (F21)	114 d (70 kw)	2012.07-	Rear	Engine N47 D16 A	Joint,Propeller Shaft	537625
BMW	1 (F21)	114 i (75 kw)	2011.12-	Rear	Engine N13 B16 A	Joint,Propeller Shaft	537625
BMW	1 (F21)	116 d (85 kw)	2011.12-	Rear	Engine N47 D16 A	Joint,Propeller Shaft	537625
BMW	1 (F21)	116 d (85 kw)	2012.01-	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	1 (F21)	116 i (100 kw)	2011.12-	Rear	Engine N13 B16 A	Joint,Propeller Shaft	537625
BMW	1 (F21)	116 i (80 kw)	2015.03-	Rear	Engine B38 B15 A	Joint,Propeller Shaft	537625
BMW	1 (F21)	118 d (100 kw)	2011.12-	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	1 (F21)	118 d (105 kw)	2011.12-	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	1 (F21)	118 d (110 kw)	2015.03-	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	1 (F21)	118 d xDrive (105 kw)	2013.05-	Rear	AWD Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	1 (F21)	118 i (100 kw)	2015.03-	Rear	Engine B38 B15 A	Joint,Propeller Shaft	537625
BMW	1 (F21)	118 i (100 kw)	2015.03-	Rear	Engine N13 B16 A	Joint,Propeller Shaft	537625
BMW	1 (F21)	118 i (125 kw)	2012.07-	Rear	Engine N13 B16 A	Joint,Propeller Shaft	537625
BMW	1 (F21)	120 d (120 kw)	2012.07-	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	1 (F21)	120 d (135 kw)	2012.07-	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	1 (F21)	120 d (140 kw)	2015.03-	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	1 (F21)	120 d (147 kw)	2012.01-	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	1 (F21)	120 d xDrive (135 kw)	2012.02-	Rear	AWD Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	1 (F21)	120 d xDrive (140 kw)	2015.03-	Rear	AWD Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	1 (F21)	120 d xDrive (147 kw)	2012.01-	Rear	AWD Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	1 (F21)	120 i (130 kw)	2015.03-	Rear	Engine N13 B16 A	Joint,Propeller Shaft	537625
BMW	1 (F21)	120 i (135 kw)	2016.07-	Rear	Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	1 (F21)	125 d (160 kw)	2011.12-	Rear	Engine N47 D20 D	Joint,Propeller Shaft	537631
BMW	1 (F21)	125 i (160 kw)	2011.12-	Rear	Engine N20 B20 A	Joint,Propeller Shaft	537625
BMW	1 (F21)	125 i (165 kw)	2015.10-	Rear	Engine B48 B20 B	Joint,Propeller Shaft	537625
BMW	1 (F21)	125 i (175 kw)	2013.03-	Rear	Engine N20 B20 A	Joint,Propeller Shaft	537625
BMW	1 (F21)	125 i Active Flex (160 kw)	2014.08-	Rear	Engine N20 B20 A	Joint,Propeller Shaft	537625
BMW	2 (F23)	218 d (100 kw)	2015.07-	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	2 (F23)	218 d (110 kw)	2015.07-	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	2 (F23)	218 i (100 kw)	2015.03-	Rear	Engine B38 B15 A	Joint,Propeller Shaft	537625
BMW	2 (F23)	220 d (120 kw)	2014.03-	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	2 (F23)	220 d (140 kw)	2014.03-	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	2 (F23)	220 i (135 kw)	2014.04-2016.07	Rear	Engine N20 B20 A, N20 B20 B	Joint,Propeller Shaft	537625
BMW	2 (F23)	220 i (135 kw)	2015.09-	Rear	Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	2 (F23)	228 i (180 kw)	2014.11-	Rear	Engine N20 B20 A	Joint,Propeller Shaft	537625
BMW	2 (F23)	230 i (185 kw)	2016.07-	Rear	Engine B46 B20 B, B48 B20 B	Joint,Propeller Shaft	537625
BMW	2 Coupe (F22, F87)	218 d (100 kw)	2014.03-	Rear	Engine B47 D20 A (07.15-), N47 D20 C (03.14-06.15)	Joint,Propeller Shaft	537625
BMW	2 Coupe (F22, F87)	218 d (105 kw)	2014.03-2015.06	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	2 Coupe (F22, F87)	218 d (110 kw)	2015.07-	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	2 Coupe (F22, F87)	218 i (100 kw)	2015.03-	Rear	Engine B38 B15 A	Joint,Propeller Shaft	537625
BMW	2 Coupe (F22, F87)	220 d (120 kw)	2014.11-	Rear	Engine B47 D20 A, N47 D20 C	Joint,Propeller Shaft	537625
BMW	2 Coupe (F22, F87)	220 d (135 kw)	2012.10-2014.11	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	2 Coupe (F22, F87)	220 d (140 kw)	2014.03-	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	2 Coupe (F22, F87)	220 d (147 kw)	2012.10-2014.11	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	2 Coupe (F22, F87)	220 d xDrive (120 kw)	2015.03-	Rear	AWD Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	2 Coupe (F22, F87)	220 d xDrive (140 kw)	2014.06-	Rear	AWD Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	2 Coupe (F22, F87)	220 i (135 kw)	2013.10-	Rear	Engine N20 B20 A, N20 B20 B	Joint,Propeller Shaft	537625
BMW	2 Coupe (F22, F87)	220 i (135 kw)	2015.09-	Rear	Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	2 Coupe (F22, F87)	228 i (180 kw)	2014.07-	Rear	Engine N20 B20 A, N26 B20 A	Joint,Propeller Shaft	537625
BMW	2 Coupe (F22, F87)	230 i (185 kw)	2016.07-	Rear	Engine B46 B20 B, B48 B20 B	Joint,Propeller Shaft	537625
BMW	3 (E46)	325 xi (141 kw)	2000.09-2005.02	Rear	AWD Engine M54 B25 (256S5)	Joint,Propeller Shaft	537631
BMW	3 (E46)	330 xi (170 kw)	2000.06-2005.02	Rear	AWD Engine M54 B30 (306S3)	Joint,Propeller Shaft	537631
BMW	3 (F30, F80)	316 d (85 kw)	2012.03-2018.10	Rear	Engine B47 D20 A, N47 D20 C	Joint,Propeller Shaft	537625

MANUFACTURER	MODEL	DISPLACEMENT	YEAR	REMARK	FITTING POSITION	PRODUCT	GSP NO.
BMW	3 (F30, F80)	316 i (100 kw)	2012.07-2016.08	Rear	Engine N13 B16 A	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	318 d (100 kw)	2012.03-2018.10	Rear	Engine B47 D20 A, N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	318 d (105 kw)	2012.03-2015.06	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	318 d (110 kw)	2015.07-2018.10	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	318 d xDrive (105 kw)	2013.07-2015.06	Rear	AWD Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	318 d xDrive (110 kw)	2015.07-2018.02	Rear	AWD Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	318 i (100 kw)	2015.07-2018.10	Rear	Engine B38 B15 A	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	320 d (120 kw)	2011.11-2018.10	Rear	Engine B47 D20 A, N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	320 d (135 kw)	2011.11-2016.03	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	320 d (140 kw)	2015.07-2018.10	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	320 d (147 kw)	2011.11-2016.03	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	320 d xDrive (120 kw)	2012.08-2018.10	Rear	AWD Engine B47 D20 A, N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	320 d xDrive (135 kw)	2012.08-2015.06	Rear	AWD Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	320 d xDrive (140 kw)	2015.07-2018.10	Rear	AWD Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	320 d xDrive (147 kw)	2012.08-2015.06	Rear	AWD Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	320 i (125 kw)	2012.11-2016.06	Rear	Engine N13 B16 A	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	320 i (135 kw)	2012.03-2018.10	Rear	Engine N20 B20 A, N20 B20 B, N20 B20 D	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	320 i (135 kw)	2015.07-2018.10	Rear	Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	320 i xDrive (135 kw)	2012.07-2018.10	Rear	AWD Engine N20 B20 A, N20 B20 B	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	320 i xDrive (135 kw)	2015.07-2018.10	Rear	AWD Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	328 i (180 kw)	2011.11-2018.10	Rear	Engine N20 B20 A, N20 B20 B, N20 B20 D, N26 B20 A	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	328 i xDrive (180 kw)	2012.07-2016.08	Rear	AWD Engine N20 B20 A, N26 B20 A	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	328i (160 kw)	2011.11-2015.06	Rear	Engine N20 B20 A	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	330 i (185 kw)	2015.07-2018.10	Rear	Engine B46 B20 B (07.16-), B48 B20 B	Joint,Propeller Shaft	537625
BMW	3 (F30, F80)	330 i xDrive (185 kw)	2015.07-2018.10	Rear	AWD Engine B46 B20 B (07.16-), B48 B20 A, B48 B20 B	Joint,Propeller Shaft	537625
BMW	3 (G20)	318 d (100 kw)	2019.03-	Front	Engine B47 D20 B	Joint,Propeller Shaft	533422
BMW	3 (G20)	318 d (100 kw)	2019.03-	Rear	Engine B47 D20 B	Joint,Propeller Shaft	537625
BMW	3 (G20)	318 d (110 kw)	2019.03-	Front	Engine B47 D20 B	Joint,Propeller Shaft	533422
BMW	3 (G20)	318 d (110 kw)	2019.03-	Rear	Engine B47 D20 B	Joint,Propeller Shaft	537625
BMW	3 (G20)	320 d xDrive (120 kw)	2018.11-	Rear	AWD Engine B47 D20 B	Joint,Propeller Shaft	537625
BMW	3 (G20)	320 d xDrive (120 kw)	2018.11-	Rear	AWD Engine B47 D20 B	Joint,Propeller Shaft	537631
BMW	3 (G20)	320 d xDrive (140 kw)	2018.11-	Rear	AWD Engine B47 D20 B	Joint,Propeller Shaft	537625
BMW	3 (G20)	320 d xDrive (140 kw)	2018.11-	Rear	AWD Engine B47 D20 B	Joint,Propeller Shaft	537631
BMW	3 (G20)	320 i 1.6 (125 kw)	2019.03-	Front	Engine B48 B16 A	Joint,Propeller Shaft	533422
BMW	3 (G20)	320 i 1.6 (125 kw)	2019.03-	Rear	Engine B48 B16 A	Joint,Propeller Shaft	537625
BMW	3 (G20)	320 i xDrive (135 kw)	2019.07-	Rear	AWD Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	3 (G20)	320 i xDrive (135 kw)	2019.07-	Rear	AWD Engine B48 B20 A	Joint,Propeller Shaft	537631
BMW	3 (G20)	330 d xDrive (195 kw)	2019.07-	Rear	AWD Engine B57 D30 A	Joint,Propeller Shaft	537625
BMW	3 (G20)	330 d xDrive (195 kw)	2019.07-	Rear	AWD Engine B57 D30 A	Joint,Propeller Shaft	537631
BMW	3 (G20)	330 i xDrive (190 kw)	2018.11-	Rear	AWD Engine B46 B20 B, B48 B20 B	Joint,Propeller Shaft	537625
BMW	3 (G20)	330 i xDrive (190 kw)	2018.11-	Rear	AWD Engine B46 B20 B, B48 B20 B	Joint,Propeller Shaft	537631
BMW	3 (G20)	M 340 i xDrive (275 kw)	2019.07-	Rear	AWD Engine B58 B30 B	Joint,Propeller Shaft	537625
BMW	3 (G20)	M 340 i xDrive (275 kw)	2019.07-	Rear	AWD Engine B58 B30 B	Joint,Propeller Shaft	537631
BMW	3 (G20)	M 340 i xDrive (285 kw)	2019.03-	Rear	AWD Engine B58 B30 B	Joint,Propeller Shaft	537625
BMW	3 (G20)	M 340 i xDrive (285 kw)	2019.03-	Rear	AWD Engine B58 B30 B	Joint,Propeller Shaft	537631
BMW	3 Gran Turismo (F34)	318 d (100 kw)	2013.03-	Rear	Engine B47 D20 A (07.15-), N47 D20 C (-06.15)	Joint,Propeller Shaft	537625
BMW	3 Gran Turismo (F34)	318 d (105 kw)	2013.03-2015.06	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 Gran Turismo (F34)	318 d (110 kw)	2015.07-	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	3 Gran Turismo (F34)	320 d (120 kw)	2013.03-	Rear	Engine B47 D20 A (07.15-), N47 D20 C (-06.15)	Joint,Propeller Shaft	537625
BMW	3 Gran Turismo (F34)	320 d (135 kw)	2013.03-2015.06	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 Gran Turismo (F34)	320 d (140 kw)	2015.07-	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	3 Gran Turismo (F34)	320 d (147 kw)	2013.03-2015.06	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 Gran Turismo (F34)	320 d xDrive (120 kw)	2013.07-	Rear	AWD Engine B47 D20 A (07.15-), N47 D20 C (-06.15)	Joint,Propeller Shaft	537625
BMW	3 Gran Turismo (F34)	320 d xDrive (135 kw)	2013.07-2015.06	Rear	AWD Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 Gran Turismo (F34)	320 d xDrive (140 kw)	2015.07-	Rear	AWD Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	3 Gran Turismo (F34)	320 d xDrive (147 kw)	2013.07-2015.06	Rear	AWD Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 Gran Turismo (F34)	320 i (120 kw)	2013.03-2016.06	Rear	Engine N20 B20 A, N20 B20 B	Joint,Propeller Shaft	537625
BMW	3 Gran Turismo (F34)	320 i (120 kw)	2016.07-	Rear	Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	3 Gran Turismo (F34)	320 i (135 kw)	2013.03-2016.06	Rear	Engine N20 B20 A, N20 B20 B	Joint,Propeller Shaft	537625
BMW	3 Gran Turismo (F34)	320 i (135 kw)	2016.07-	Rear	Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	3 Gran Turismo (F34)	320 i xDrive (120 kw)	2013.07-2016.06	Rear	AWD Engine N20 B20 A, N20 B20 B	Joint,Propeller Shaft	537625

MANUFACTURER	MODEL	DISPLACEMENT	YEAR	REMARK	FITTING POSITION	PRODUCT	GSP NO.
BMW	3 Gran Turismo (F34)	320 i xDrive (120 kw)	2016.07-	Rear	AWD Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	3 Gran Turismo (F34)	320 i xDrive (135 kw)	2012.11-2016.06	Rear	AWD Engine N20 B20 A, N20 B20 B	Joint,Propeller Shaft	537625
BMW	3 Gran Turismo (F34)	320 i xDrive (135 kw)	2016.07-	Rear	AWD Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	3 Gran Turismo (F34)	328 i (180 kw)	2013.03-2016.06	Rear	Engine N20 B20 A, N26 B20 A (07.14-06.15)	Joint,Propeller Shaft	537625
BMW	3 Gran Turismo (F34)	328 i xDrive (180 kw)	2013.07-2016.06	Rear	AWD Engine N20 B20 A, N26 B20 A (07.14-)	Joint,Propeller Shaft	537625
BMW	3 Gran Turismo (F34)	330 i (185 kw)	2016.07-	Rear	Engine B48 B20 B	Joint,Propeller Shaft	537625
BMW	3 Touring (E46)	325 xi (141 kw)	2000.09-2005.02	Rear	AWD Engine M54 B25 (256S5)	Joint,Propeller Shaft	537631
BMW	3 Touring (E46)	330 xd (150 kw)	2002.08-2005.05	Rear	AWD Engine M57 D30 (306D2)	Joint,Propeller Shaft	537631
BMW	3 Touring (E46)	330 xi (170 kw)	2000.06-2005.02	Rear	AWD Engine M54 B30 (306S3)	Joint,Propeller Shaft	537631
BMW	3 Touring (F31)	316 d (85 kw)	2012.11-2019.06	Rear	Engine B47 D20 A, N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	316 i (100 kw)	2013.03-2015.06	Rear	Engine N13 B16 A	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	318 d (100 kw)	2012.11-2019.06	Rear	Engine B47 D20 A, N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	318 d (105 kw)	2012.11-2015.06	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	318 d (110 kw)	2015.07-2019.06	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	318 d xDrive (105 kw)	2013.07-2015.06	Rear	AWD Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	318 d xDrive (110 kw)	2015.07-2018.02	Rear	AWD Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	318 i (100 kw)	2015.07-2019.06	Rear	Engine B38 B15 A	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	320 d (120 kw)	2012.07-2019.06	Rear	Engine B47 D20 A, N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	320 d (135 kw)	2012.07-2016.02	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	320 d (140 kw)	2015.07-2019.06	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	320 d (147 kw)	2012.07-2016.02	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	320 d xDrive (120 kw)	2013.03-2019.06	Rear	AWD Engine B47 D20 A (07.15-), N47 D20 C (-08.15)	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	320 d xDrive (135 kw)	2013.03-2015.06	Rear	AWD Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	320 d xDrive (140 kw)	2015.07-2019.06	Rear	AWD Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	320 d xDrive (147 kw)	2013.03-2015.06	Rear	AWD Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	320 i (120 kw)	2012.11-2015.06	Rear	Engine N20 B20 B	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	320 i (135 kw)	2012.11-2015.06	Rear	Engine N20 B20 B	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	320 i (135 kw)	2015.07-2019.06	Rear	Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	320 i xDrive (120 kw)	2013.03-2015.06	Rear	AWD Engine N20 B20 B	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	320 i xDrive (135 kw)	2013.03-2015.06	Rear	AWD Engine N20 B20 B	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	320 i xDrive (135 kw)	2015.07-2019.06	Rear	AWD Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	328 i (180 kw)	2012.07-2015.06	Rear	Engine N20 B20 A	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	328 i xDrive (180 kw)	2013.03-2016.06	Rear	AWD Engine N20 B20 A	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	330 i (185 kw)	2015.07-2019.06	Rear	Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	3 Touring (F31)	330 i xDrive (185 kw)	2015.07-2019.06	Rear	AWD Engine B48 B20 A, B48 B20 B	Joint,Propeller Shaft	537625
BMW	3 Touring (G21)	320 d xDrive (120 kw)	2019.07-	Rear	AWD Engine B47 D20 B	Joint,Propeller Shaft	537625
BMW	3 Touring (G21)	320 d xDrive (140 kw)	2019.07-	Rear	AWD Engine B47 D20 B	Joint,Propeller Shaft	537625
BMW	3 Touring (G21)	330 d xDrive (195 kw)	2019.07-	Rear	AWD Engine B57 D30 A	Joint,Propeller Shaft	537631
BMW	3 Touring (G21)	330 i xDrive (190 kw)	2019.07-	Rear	AWD Engine B48 B20 B	Joint,Propeller Shaft	537625
BMW	3 Touring (G21)	330 i xDrive (190 kw)	2019.07-	Rear	AWD Engine B48 B20 B	Joint,Propeller Shaft	537631
BMW	3 Touring (G21)	M 340 i xDrive (275 kw)	2019.11-	Rear	AWD Engine B58 B30 B	Joint,Propeller Shaft	537631
BMW	4 (F33, F83)	420 d (120 kw)	2013.11-	Rear	Engine B47 D20 A (07.15-), N47 D20 C (-08.15)	Joint,Propeller Shaft	537625
BMW	4 (F33, F83)	420 d (135 kw)	2013.10-2015.06	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	4 (F33, F83)	420 d (140 kw)	2015.07-	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	4 (F33, F83)	420 d (147 kw)	2013.10-2015.06	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	4 (F33, F83)	420 i (120 kw)	2014.07-2016.02	Rear	Engine N20 B20 B	Joint,Propeller Shaft	537625
BMW	4 (F33, F83)	420 i (120 kw)	2016.03-	Rear	Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	4 (F33, F83)	420 i (135 kw)	2014.07-2016.02	Rear	Engine N20 B20 B	Joint,Propeller Shaft	537625
BMW	4 (F33, F83)	420 i (135 kw)	2016.03-	Rear	Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	4 (F33, F83)	428 i (180 kw)	2013.11-2017.02	Rear	Engine N20 B20 A (-02.16), N26 B20 A (-02.17)	Joint,Propeller Shaft	537625
BMW	4 (F33, F83)	428 i xDrive (180 kw)	2014.03-2016.02	Rear	AWD Engine N20 B20 A (-02.16), N26 B20 A	Joint,Propeller Shaft	537625
BMW	4 (F33, F83)	430 i (185 kw)	2016.03-	Rear	Engine B46 B20 B (07.16-), B48 B20 B (03.16-)	Joint,Propeller Shaft	537625
BMW	4 (F33, F83)	430 i xDrive (185 kw)	2016.03-	Rear	AWD Engine B46 B20 B (07.16-), B48 B20 B (03.16-)	Joint,Propeller Shaft	537625
BMW	4 Coupe (F32, F82)	418 d (100 kw)	2015.03-2017.10	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	4 Coupe (F32, F82)	418 d (110 kw)	2015.03-2017.10	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	4 Coupe (F32, F82)	418 i (100 kw)	2016.03-	Rear	Engine B38 B15 A	Joint,Propeller Shaft	537625
BMW	4 Coupe (F32, F82)	420 d (120 kw)	2013.07-	Rear	Engine B47 D20 A (03.15-), N47 D20 C (-02.15)	Joint,Propeller Shaft	537625
BMW	4 Coupe (F32, F82)	420 d (135 kw)	2013.07-2015.02	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	4 Coupe (F32, F82)	420 d (140 kw)	2015.03-	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	4 Coupe (F32, F82)	420 d (147 kw)	2013.07-2015.03	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	4 Coupe (F32, F82)	420 d xDrive (120 kw)	2013.11-	Rear	AWD Engine B47 D20 A (03.15-), N47 D20 C (-02.15)	Joint,Propeller Shaft	537625

MANUFACTURER	MODEL	DISPLACEMENT	YEAR	REMARK	FITTING POSITION	PRODUCT	GSP NO.
BMW	4 Coupe (F32, F82)	420 d xDrive (135 kw)	2013.11-2015.02	Rear	AWD Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	4 Coupe (F32, F82)	420 d xDrive (140 kw)	2015.03-	Rear	AWD Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	4 Coupe (F32, F82)	420 d xDrive (147 kw)	2013.11-2015.03	Rear	AWD Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	4 Coupe (F32, F82)	420 i (120 kw)	2016.03-	Rear	Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	4 Coupe (F32, F82)	420 i (135 kw)	2013.11-2017.02	Rear	Engine N20 B20 A, N20 B20 B	Joint,Propeller Shaft	537625
BMW	4 Coupe (F32, F82)	420 i (135 kw)	2016.03-	Rear	Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	4 Coupe (F32, F82)	420 i xDrive (120 kw)	2013.11-2016.02	Rear	AWD Engine N20 B20 A, N20 B20 B	Joint,Propeller Shaft	537625
BMW	4 Coupe (F32, F82)	420 i xDrive (120 kw)	2016.03-	Rear	AWD Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	4 Coupe (F32, F82)	420 i xDrive (135 kw)	2013.11-2016.02	Rear	AWD Engine N20 B20 A, N20 B20 B	Joint,Propeller Shaft	537625
BMW	4 Coupe (F32, F82)	420 i xDrive (135 kw)	2016.03-	Rear	AWD Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	4 Coupe (F32, F82)	428 i (180 kw)	2013.07-2017.02	Rear	Engine N20 B20 A (-06.16), N26 B20 A	Joint,Propeller Shaft	537625
BMW	4 Coupe (F32, F82)	428 i xDrive (180 kw)	2013.07-2016.02	Rear	AWD Engine N20 B20 A (-02.16), N26 B20 A	Joint,Propeller Shaft	537625
BMW	4 Coupe (F32, F82)	430 i (185 kw)	2016.03-	Rear	Engine B46 B20 B (07.16-), B48 B20 B	Joint,Propeller Shaft	537625
BMW	4 Coupe (F32, F82)	430 i xDrive (185 kw)	2016.03-	Rear	AWD Engine B46 B20 B (07.16-), B48 B20 B	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	418 d (100 kw)	2014.03-	Rear	Engine B47 D20 A (07.15-), N47 D20 C (-06.15)	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	418 d (105 kw)	2014.03-2015.06	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	418 d (110 kw)	2015.07-	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	418 i (100 kw)	2015.07-	Rear	Engine B38 B15 A	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	420 d (120 kw)	2014.03-	Rear	Engine B47 D20 A (03.15-), N47 D20 C (-02.15)	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	420 d (135 kw)	2014.03-2015.02	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	420 d (140 kw)	2015.03-	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	420 d (147 kw)	2014.03-2015.02	Rear	Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	420 d xDrive (120 kw)	2014.03-	Rear	AWD Engine B47 D20 A (03.15-), N47 D20 C (-02.15)	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	420 d xDrive (135 kw)	2014.03-2015.02	Rear	AWD Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	420 d xDrive (140 kw)	2015.03-	Rear	AWD Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	420 d xDrive (147 kw)	2014.03-2015.02	Rear	AWD Engine N47 D20 C	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	420 i (120 kw)	2014.03-2017.02	Rear	Engine N20 B20 B	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	420 i (120 kw)	2016.03-	Rear	Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	420 i (135 kw)	2014.03-2017.02	Rear	Engine N20 B20 B	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	420 i (135 kw)	2016.03-	Rear	Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	420 i xDrive (120 kw)	2014.07-2016.02	Rear	AWD Engine N20 B20 B	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	420 i xDrive (120 kw)	2016.03-	Rear	AWD Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	420 i xDrive (135 kw)	2014.07-2016.02	Rear	AWD Engine N20 B20 B	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	420 i xDrive (135 kw)	2016.03-	Rear	AWD Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	428 i (180 kw)	2014.03-2016.06	Rear	Engine N20 B20 A, N26 B20 A	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	428 i xDrive (180 kw)	2014.03-2016.02	Rear	AWD Engine N20 B20 A, N26 B20 A	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	430 i (185 kw)	2016.03-	Rear	Engine B46 B20 B (07.16-), B48 B20 B	Joint,Propeller Shaft	537625
BMW	4 Gran Coupe (F36)	430 i xDrive (185 kw)	2016.03-	Rear	AWD Engine B46 B20 B (07.16-), B48 B20 B	Joint,Propeller Shaft	537625
BMW	5 (E60)	520 d (110 kw)	2005.09-2007.02	Front	Engine M47 D20 (204D4)	Joint,Propeller Shaft	533422
BMW	5 (E60)	520 d (120 kw)	2005.09-2009.12	Front	Engine M47 D20 (204D4), N47 D20 C	Joint,Propeller Shaft	533422
BMW	5 (E60)	520 d (130 kw)	2007.09-2009.12	Front	Engine N47 D20 A, N47 D20 C (09.08-)	Joint,Propeller Shaft	533422
BMW	5 (E60)	520 i (115 kw)	2007.09-2010.02	Front	Engine N46 B20 B	Joint,Propeller Shaft	533422
BMW	5 (E60)	520 i (125 kw)	2003.07-2010.03	Front	Engine M54 B22 (226S1)	Joint,Propeller Shaft	533422
BMW	5 (E60)	520 i (125 kw)	2007.09-2009.12	Front	Engine N43 B20 A	Joint,Propeller Shaft	533422
BMW	5 (E60)	523 i (130 kw)	2004.10-2007.02	Front	Engine N52 B25 A, N52 B25 B, N52 B25 BE	Joint,Propeller Shaft	533422
BMW	5 (E60)	523 i (140 kw)	2007.03-2009.12	Front	Engine N52 B25 A, N52 B25 BE	Joint,Propeller Shaft	533422
BMW	5 (E60)	523 i (140 kw)	2007.03-2009.12	Front	Engine N53 B25 A	Joint,Propeller Shaft	533422
BMW	5 (E60)	525 i (141 kw)	2003.09-2005.02	Front	Engine M54 B25 (256S5)	Joint,Propeller Shaft	533422
BMW	5 (E60)	525 i (160 kw)	2005.03-2009.12	Front	Engine N52 B25 A, N52 B25 B, N52 B25 BF	Joint,Propeller Shaft	533422
BMW	5 (E60)	525 i (160 kw)	2007.01-2010.03	Front	Engine N53 B30 A	Joint,Propeller Shaft	533422
BMW	5 (E60)	530 i (170 kw)	2001.12-2005.02	Front	Engine M54 B30 (306S3)	Joint,Propeller Shaft	533422
BMW	5 (E60)	530 i (190 kw)	2005.03-2007.03	Front	Engine N52 B30 A, N52 B30 BF	Joint,Propeller Shaft	533422
BMW	5 (E60)	530 i (200 kw)	2007.03-2009.12	Front	Engine N53 B30 A	Joint,Propeller Shaft	533422
BMW	5 (F10)	520 d xDrive (135 kw)	2013.07-2014.06	Rear	AWD Engine N47 D20 C	Joint,Propeller Shaft	537631
BMW	5 (F10)	520 i (120 kw)	2011.09-2016.10	Rear	Engine N20 B20 A, N20 B20 B	Joint,Propeller Shaft	537625
BMW	5 (F10)	520 i (125 kw)	2013.07-2016.10	Rear	Engine N20 B16 A	Joint,Propeller Shaft	537625
BMW	5 (F10)	520 i (135 kw)	2011.09-2016.10	Front	Engine N20 B20 A, N20 B20 B	Joint,Propeller Shaft	533422
BMW	5 (F10)	520 i (135 kw)	2011.09-2016.10	Rear	Engine N20 B20 A, N20 B20 B	Joint,Propeller Shaft	537625
BMW	5 (F10)	523 i (150 kw)	2009.06-2011.08	Front	Engine N53 B30 A	Joint,Propeller Shaft	533422
BMW	5 (F10)	523 i (150 kw)	2009.06-2011.08	Rear	Engine N53 B30 A	Joint,Propeller Shaft	537625
BMW	5 (F10)	523 i (150 kw)	2010.01-2011.08	Front	Engine N52 B25 A, N52 B25 AF, N52 B25 B, N52 B25 BF	Joint,Propeller Shaft	533422

MANUFACTURER	MODEL	DISPLACEMENT	YEAR	REMARK	FITTING POSITION	PRODUCT	GSP NO.
BMW	5 (F10)	523 i (150 kw)	2010.01-2011.08	Rear	Engine N52 B25 A, N52 B25 AF, N52 B25 B, N52 B25 BF	Joint,Propeller Shaft	537625
BMW	5 (F10)	523 i (155 kw)	2010.01-2011.08	Rear	Engine N53 B30 A	Joint,Propeller Shaft	537625
BMW	5 (F10)	525 d (160 kw)	2011.09-2016.10	Rear	Engine N47 D20 D	Joint,Propeller Shaft	537631
BMW	5 (F10)	525 d xDrive (160 kw)	2011.09-2016.10	Rear	AWD Engine N47 D20 D	Joint,Propeller Shaft	537631
BMW	5 (F10)	528 i (180 kw)	2011.09-2016.10	Front	Engine N20 B20 A	Joint,Propeller Shaft	533422
BMW	5 (F10)	528 i (180 kw)	2011.09-2016.10	Rear	Engine N20 B20 A	Joint,Propeller Shaft	537625
BMW	5 (F10)	528 i (190 kw)	2010.03-2011.08	Front	Engine N53 B30 A	Joint,Propeller Shaft	533422
BMW	5 (F10)	528 i (190 kw)	2010.03-2011.08	Rear	Engine N53 B30 A	Joint,Propeller Shaft	537625
BMW	5 (F10)	528 i xDrive (180 kw)	2011.09-2016.10	Rear	AWD Engine N20 B20 A	Joint,Propeller Shaft	537631
BMW	5 (F10)	530 i (190 kw)	2010.03-2013.06	Rear	Engine N52 B30 A, N52 B30 AF, N52 B30 BF	Joint,Propeller Shaft	537625
BMW	5 (F10)	530 i (200 kw)	2011.05-2013.06	Front	Engine N53 B30 A	Joint,Propeller Shaft	533422
BMW	5 (F10)	530 i (200 kw)	2011.05-2013.06	Rear	Engine N53 B30 A	Joint,Propeller Shaft	537625
BMW	5 (G30, F90)	518 d (100 kw)	2018.07-	Rear	Engine B47 D20 B	Joint,Propeller Shaft	537625
BMW	5 (G30, F90)	518 d (110 kw)	2018.07-	Rear	Engine B47 D20 B	Joint,Propeller Shaft	537625
BMW	5 (G30, F90)	520 d (120 kw)	2016.09-	Rear	Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	5 (G30, F90)	520 d (140 kw)	2016.09-	Rear	Engine B47 D20 A, B47 D20 B	Joint,Propeller Shaft	537625
BMW	5 (G30, F90)	520 d xDrive (120 kw)	2016.09-	Rear	AWD Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	5 (G30, F90)	520 d xDrive (140 kw)	2016.09-	Rear	AWD Engine B47 D20 A	Joint,Propeller Shaft	537625
BMW	5 (G30, F90)	520 i (120 kw)	2017.07-	Rear	Engine B48 B20 A, B48 B20 B (07.18-.)	Joint,Propeller Shaft	537625
BMW	5 (G30, F90)	520 i (125 kw)	2017.07-	Rear	Engine B48 B16 A	Joint,Propeller Shaft	537625
BMW	5 (G30, F90)	520 i (135 kw)	2017.07-	Rear	Engine B48 B20 A, B48 B20 B (07.18-.)	Joint,Propeller Shaft	537625
BMW	5 (G30, F90)	520 i (155 kw)	2017.07-	Rear	Engine B48 B20 A, B48 B20 B (07.18-.)	Joint,Propeller Shaft	537625
BMW	5 (G30, F90)	530 i (185 kw)	2016.09-	Rear	Engine B46 B20 B, B48 B20 B	Joint,Propeller Shaft	537625
BMW	5 (G30, F90)	530 i xDrive (185 kw)	2016.09-	Rear	AWD Engine B46 B20 B, B48 B20 B	Joint,Propeller Shaft	537625
BMW	5 Gran Turismo (F07)	528 i (180 kw)	2013.07-2017.02	Rear	Engine N20 B20 A	Joint,Propeller Shaft	537625
BMW	5 Touring (E61)	520 d (120 kw)	2005.04-2010.05	Front	Engine M47 D20 (204D4), N47 D20 C	Joint,Propeller Shaft	533422
BMW	5 Touring (E61)	520 i (125 kw)	2007.09-2010.12	Front	Engine N43 B20 A	Joint,Propeller Shaft	533422
BMW	5 Touring (E61)	523 i (130 kw)	2004.10-2007.02	Front	Engine N52 B25 A, N52 B25 B, N52 B25 BE	Joint,Propeller Shaft	533422
BMW	5 Touring (E61)	523 i (140 kw)	2007.01-2010.12	Front	Engine N53 B25 A	Joint,Propeller Shaft	533422
BMW	5 Touring (E61)	525 i (141 kw)	2004.06-2010.12	Front	Engine M54 B25 (256S5)	Joint,Propeller Shaft	533422
BMW	5 Touring (E61)	525 i (160 kw)	2005.03-2010.05	Front	Engine N52 B25 A, N52 B25 B, N52 B25 BF	Joint,Propeller Shaft	533422
BMW	5 Touring (E61)	525 i (160 kw)	2007.01-2010.12	Front	Engine N53 B30 A	Joint,Propeller Shaft	533422
BMW	5 Touring (E61)	530 i (190 kw)	2004.09-2007.02	Front	Engine N52 B30 A, N52 B30 BF	Joint,Propeller Shaft	533422
BMW	5 Touring (E61)	530 i (200 kw)	2007.01-2010.12	Front	Engine N53 B30 A	Joint,Propeller Shaft	533422
BMW	5 Touring (F11)	520 d xDrive (135 kw)	2013.07-2014.06	Rear	AWD Engine N47 D20 C	Joint,Propeller Shaft	537631
BMW	5 Touring (F11)	520 i (120 kw)	2011.09-2017.02	Rear	Engine N20 B20 A, N20 B20 B	Joint,Propeller Shaft	537625
BMW	5 Touring (F11)	520 i (135 kw)	2010.10-2017.02	Front	Engine N20 B20 A, N20 B20 B	Joint,Propeller Shaft	533422
BMW	5 Touring (F11)	520 i (135 kw)	2010.10-2017.02	Rear	Engine N20 B20 A, N20 B20 B	Joint,Propeller Shaft	537625
BMW	5 Touring (F11)	523 i (150 kw)	2009.11-2011.08	Front	Engine N52 B25 A, N52 B25 AF, N52 B25 B	Joint,Propeller Shaft	533422
BMW	5 Touring (F11)	523 i (150 kw)	2009.11-2011.08	Rear	Engine N52 B25 A, N52 B25 AF, N52 B25 B	Joint,Propeller Shaft	537625
BMW	5 Touring (F11)	523 i (150 kw)	2009.11-2011.08	Front	Engine N53 B30 A	Joint,Propeller Shaft	533422
BMW	5 Touring (F11)	523 i (150 kw)	2009.11-2011.08	Rear	Engine N53 B30 A	Joint,Propeller Shaft	537625
BMW	5 Touring (F11)	525 d (160 kw)	2011.09-2017.02	Rear	Engine N47 D20 D	Joint,Propeller Shaft	537631
BMW	5 Touring (F11)	525 d xDrive (160 kw)	2013.07-2017.02	Rear	AWD Engine N47 D20 D	Joint,Propeller Shaft	537631
BMW	5 Touring (F11)	528 i (180 kw)	2011.09-2017.02	Front	Engine N20 B20 A	Joint,Propeller Shaft	533422
BMW	5 Touring (F11)	528 i (180 kw)	2011.09-2017.02	Rear	Engine N20 B20 A	Joint,Propeller Shaft	537625
BMW	5 Touring (F11)	528 i (190 kw)	2009.11-2011.08	Front	Engine N53 B30 A	Joint,Propeller Shaft	533422
BMW	5 Touring (F11)	528 i (190 kw)	2009.11-2011.08	Rear	Engine N53 B30 A	Joint,Propeller Shaft	537625
BMW	5 Touring (F11)	528 i xDrive (180 kw)	2011.09-2017.02	Rear	AWD Engine N20 B20 A	Joint,Propeller Shaft	537631
BMW	5 Touring (F11)	530 i (190 kw)	2010.03-2013.05	Rear	Engine N52 B30 A, N52 B30 AF	Joint,Propeller Shaft	537625
BMW	5 Touring (F11)	530 i (200 kw)	2011.07-2013.06	Front	Engine N53 B30 A	Joint,Propeller Shaft	533422
BMW	5 Touring (F11)	530 i (200 kw)	2011.07-2013.06	Rear	Engine N53 B30 A	Joint,Propeller Shaft	537625
BMW	5 Touring (G31)	520 d (120 kw)	2017.03-	Rear	Engine B47 D20 A, B47 D20 B (07.18-.)	Joint,Propeller Shaft	537625
BMW	5 Touring (G31)	520 d (140 kw)	2017.03-	Rear	Engine B47 D20 A, B47 D20 B (07.18-.)	Joint,Propeller Shaft	537625
BMW	5 Touring (G31)	520 d xDrive (120 kw)	2017.07-	Rear	AWD Engine B47 D20 A, B47 D20 B (07.18-.)	Joint,Propeller Shaft	537625
BMW	5 Touring (G31)	520 d xDrive (140 kw)	2017.07-	Rear	AWD Engine B47 D20 A, B47 D20 B (07.18-.)	Joint,Propeller Shaft	537625
BMW	5 Touring (G31)	520 i (120 kw)	2017.07-	Rear	Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	5 Touring (G31)	520 i (135 kw)	2017.07-	Rear	Engine B48 B20 A	Joint,Propeller Shaft	537625
BMW	5 Touring (G31)	530 i (185 kw)	2017.03-	Rear	Engine B48 B20 B	Joint,Propeller Shaft	537625
BMW	5 Touring (G31)	530 i xDrive (185 kw)	2017.07-	Rear	AWD Engine B48 B20 B	Joint,Propeller Shaft	537625

MANUFACTURER	MODEL	DISPLACEMENT	YEAR	REMARK	FITTING POSITION	PRODUCT	GSP NO.
BMW	6 (E63)	630 i (190 kw)	2004.09-2007.08	Front	Engine N52 B30 A, N52 B30 BF	Joint,Propeller Shaft	533422
BMW	6 (E63)	630 i (200 kw)	2007.09-2010.08	Front	Engine N53 B30 A	Joint,Propeller Shaft	533422
BMW	6 (E64)	630 i (190 kw)	2004.09-2007.08	Front	Engine N52 B30 A, N52 B30 B (-03.06), N52 B30 BF	Joint,Propeller Shaft	533422
BMW	6 (E64)	630 i (200 kw)	2007.09-2010.08	Front	Engine N53 B30 A	Joint,Propeller Shaft	533422
BMW	6 Gran Turismo (G32)	630 i (183 kw)	2017.06-	Front	Engine B48 B20 B	Joint,Propeller Shaft	533422
BMW	6 Gran Turismo (G32)	630 i (183 kw)	2017.06-	Rear	Engine B48 B20 B	Joint,Propeller Shaft	537625
BMW	6 Gran Turismo (G32)	630 i (190 kw)	2017.06-	Front	Engine B48 B20 B	Joint,Propeller Shaft	533422
BMW	6 Gran Turismo (G32)	630 i (190 kw)	2017.06-	Rear	Engine B48 B20 B	Joint,Propeller Shaft	537625
BMW	7 (G11, G12)	730 i (183 kw)	2015.11-	Rear	Engine B48 B20 B	Joint,Propeller Shaft	537625
BMW	7 (G11, G12)	730 i, Li (190 kw)	2015.11-2019.02	Rear	Engine B48 B20 B	Joint,Propeller Shaft	537625
BMW	8 Gran Coupe (G16, F93)	840 i xDrive (250 kw)	2019.07-	Rear	AWD Engine B58 B30 C	Joint,Propeller Shaft	537631
BMW	X1 (E84)	sDrive 18 i (110 kw)	2010.03-2015.06	Rear	Engine N46 B20 A, N46 B20 B, N46 B20 C, N46 B20 D, N46 B20 E	Joint,Propeller Shaft	537625
BMW	X3 (E83)	2.0 d (110 kw)	2004.09-2007.08	Rear	AWD Engine M47 D20 (204D4)	Joint,Propeller Shaft	537631
BMW	X3 (E83)	2.0 i (110 kw)	2005.07-2008.08	Rear	AWD Engine N46 B20 B	Joint,Propeller Shaft	537631
BMW	X3 (E83)	2.5 i (141 kw)	2004.03-2006.07	Rear	AWD Engine M54 B25 (256S5)	Joint,Propeller Shaft	537631
BMW	X3 (E83)	3.0 d (150 kw)	2004.01-2005.08	Rear	AWD Engine M57 D30 (306D2)	Joint,Propeller Shaft	537631
BMW	X3 (E83)	3.0 i xDrive (170 kw)	2003.09-2006.07	Rear	AWD Engine M54 B30 (306S3)	Joint,Propeller Shaft	537631
BMW	X3 (E83)	xDrive 20 i (110 kw)	2008.09-2011.08	Rear	AWD Engine N46 B20 B	Joint,Propeller Shaft	537631
BMW	X3 (E83)	xDrive 30 d (160 kw)	2008.09-2010.08	Rear	AWD Engine M57 D30 (306D3)	Joint,Propeller Shaft	537631
BMW	X3 (F25)	xDrive 20 d (135 kw)	2010.09-2014.03	Rear	AWD Engine N47 D20 C	Joint,Propeller Shaft	537631
BMW	X3 (F25)	xDrive 30 d (190 kw)	2011.04-2017.08	Rear	AWD Engine N57 D30 A	Joint,Propeller Shaft	537631
BMW	X3 (F25)	xDrive 35 d (230 kw)	2011.10-2017.08	Rear	AWD Engine N57 D30 B	Joint,Propeller Shaft	537631
BMW	X3 (G01, F97)	sDrive 18 d (100 kw)	2018.04-	Front	Engine B47 D20 A, B47 D20 B (05.19-..)	Joint,Propeller Shaft	533422
BMW	X3 (G01, F97)	sDrive 18 d (110 kw)	2018.04-	Front	Engine B47 D20 A, B47 D20 B (05.19-..)	Joint,Propeller Shaft	533422
BMW	X3 (G01, F97)	sDrive 20 i (135 kw)	2017.12-	Front	Engine B48 B20 A	Joint,Propeller Shaft	533422
BMW	X3 (G01, F97)	sDrive 20 i 1.6 (125 kw)	2017.12-	Front	Engine B48 B16 A	Joint,Propeller Shaft	533422
BMW	X3 (G01, F97)	xDrive 25 d (155 kw)	2018.04-	Rear	AWD Engine B47 D20 B	Joint,Propeller Shaft	537631
BMW	X3 (G01, F97)	xDrive 25 d (170 kw)	2018.04-	Rear	AWD Engine B47 D20 B	Joint,Propeller Shaft	537631
BMW	X4 (F26)	xDrive 30 d (190 kw)	2014.04-2018.03	Rear	AWD Engine N57 D30 A	Joint,Propeller Shaft	537631
BMW	X4 (F26)	xDrive 35 d (230 kw)	2014.04-2018.03	Rear	AWD Engine N57 D30 B	Joint,Propeller Shaft	537631
BMW	X4 (G02, F98)	M40 d xDrive (240 kw)	2018.04-	Rear	AWD Engine B57 D30 B	Joint,Propeller Shaft	537631
BMW	X4 (G02, F98)	xDrive 20 d (120 kw)	2018.04-	Rear	AWD Engine B47 D20 A	Joint,Propeller Shaft	537631
BMW	X4 (G02, F98)	xDrive 20 d (140 kw)	2018.04-	Rear	AWD Engine B47 D20 A	Joint,Propeller Shaft	537631
BMW	X4 (G02, F98)	xDrive 25 d (155 kw)	2018.04-	Rear	AWD Engine B47 D20 B	Joint,Propeller Shaft	537631
BMW	X4 (G02, F98)	xDrive 25 d (170 kw)	2018.04-	Rear	AWD Engine B47 D20 B	Joint,Propeller Shaft	537631
BMW	X4 (G02, F98)	xDrive 30 d (183 kw)	2018.09-	Rear	AWD Engine B57 D30 A	Joint,Propeller Shaft	537631
BMW	X4 (G02, F98)	xDrive 30 d (195 kw)	2018.04-	Rear	AWD Engine B57 D30 A	Joint,Propeller Shaft	537631
BMW	X5 (E53)	3.0 d (155 kw)	2003.10-2006.09	Rear	AWD Engine M57 D30 (306D2)	Joint,Propeller Shaft	537631
BMW	X5 (E53)	3.0 d (160 kw)	2003.10-2006.09	Rear	AWD Engine M57 D30 (306D2)	Joint,Propeller Shaft	537631
BMW	X5 (E53)	3.0 i (170 kw)	2000.04-2006.10	Rear	AWD Engine M54 B30 (306S3)	Joint,Propeller Shaft	537631
BMW	X5 (E53)	4.4 i (235 kw)	2003.10-2006.10	Rear	AWD Engine N62 B44 A	Joint,Propeller Shaft	537631
BMW	X5 (E53)	4.8 is (265 kw)	2004.04-2006.09	Rear	AWD Engine N62 B48 A	Joint,Propeller Shaft	537631
BMW	X5 (E70)	3.0 d (173 kw)	2006.12-2008.09	Rear	AWD Engine M57 D30 (306D3)	Joint,Propeller Shaft	537631
BMW	X5 (E70)	3.0 sd (210 kw)	2007.10-2008.09	Rear	AWD Engine M57 D30 (306D5)	Joint,Propeller Shaft	537631
BMW	X5 (E70)	4.8 i xDrive (261 kw)	2006.10-2008.09	Rear	AWD Engine N62 B48 B	Joint,Propeller Shaft	537631
BMW	X5 (E70)	M (408 kw)	2009.07-2013.07	Rear	AWD Engine S63 B44 A	Joint,Propeller Shaft	537631
BMW	X5 (E70)	M 50 d (280 kw)	2011.08-2013.06	Rear	AWD Engine N57 D30 C	Joint,Propeller Shaft	537631
BMW	X5 (E70)	xDrive 30 d (180 kw)	2010.04-2013.07	Rear	AWD Engine N57 D30 A	Joint,Propeller Shaft	537631
BMW	X5 (E70)	xDrive 35 i (225 kw)	2010.04-2013.07	Rear	AWD Engine N55 B30 A	Joint,Propeller Shaft	537631
BMW	X5 (E70)	xDrive 40 d (225 kw)	2010.09-2013.06	Rear	AWD Engine N57 D30 B	Joint,Propeller Shaft	537631
BMW	X5 (E70)	xDrive 50 i (300 kw)	2010.04-2013.07	Rear	AWD Engine N63 B44 A	Joint,Propeller Shaft	537631
BMW	X5 (F15, F85)	M 50 d (280 kw)	2013.12-2018.07	Rear	AWD Engine N57 D30 C	Joint,Propeller Shaft	537631
BMW	X5 (F15, F85)	xDrive 30 d (190 kw)	2013.08-2018.07	Rear	AWD Engine N57 D30 A	Joint,Propeller Shaft	537631
BMW	X5 (F15, F85)	xDrive 35 i (225 kw)	2013.12-2018.07	Rear	AWD Engine N55 B30 A	Joint,Propeller Shaft	537631
BMW	X5 (F15, F85)	xDrive 40 d (230 kw)	2013.12-2018.07	Rear	AWD Engine N57 D30 B	Joint,Propeller Shaft	537631
BMW	X6 (E71, E72)	ActiveHybrid (357 kw)	2009.01-2011.10	Rear	AWD Engine N63 B44 A	Joint,Propeller Shaft	537631
BMW	X6 (E71, E72)	M (408 kw)	2009.07-2014.07	Rear	AWD Engine S63 B44 A	Joint,Propeller Shaft	537631
BMW	X6 (E71, E72)	xDrive 30 d (173 kw)	2008.04-2010.03	Rear	AWD Engine M57 D30 (306D3)	Joint,Propeller Shaft	537631
BMW	X6 (E71, E72)	xDrive 30 d (180 kw)	2010.04-2014.07	Rear	AWD Engine N57 D30 A	Joint,Propeller Shaft	537631
BMW	X6 (E71, E72)	xDrive 35 i (224 kw)	2008.01-2014.06	Rear	AWD Engine N54 B30 A, N55 B30 A	Joint,Propeller Shaft	537631
BMW	X6 (E71, E72)	xDrive 35 i (225 kw)	2008.01-2014.07	Rear	AWD Engine N54 B30 A, N55 B30 A	Joint,Propeller Shaft	537631

MANUFACTURER	MODEL	DISPLACEMENT	YEAR	REMARK	FITTING POSITION	PRODUCT	GSP NO.
BMW	X6 (E71, E72)	xDrive 40 d (225 kw)	2009.07-2014.06	Rear	AWD Engine N57 D30 B	Joint,Propeller Shaft	537631
BMW	X6 (E71, E72)	xDrive 50 i (300 kw)	2008.07-2014.07	Rear	AWD Engine N63 B44 A	Joint,Propeller Shaft	537631
BMW	X6 (F16, F86)	xDrive 30 d (190 kw)	2014.08-2019.07	Rear	AWD Engine N57 D30 A	Joint,Propeller Shaft	537631
BMW	X6 (F16, F86)	xDrive 35 i (225 kw)	2014.08-2019.07	Rear	AWD Engine N55 B30 A	Joint,Propeller Shaft	537631
BMW	X6 (F16, F86)	xDrive 40 d (230 kw)	2014.12-2019.07	Rear	AWD Engine N57 D30 B	Joint,Propeller Shaft	537631
BMW	X7 (G07)	xDrive 40 i (250 kw)	2019.03-	Rear	AWD Engine B58 B30 C	Joint,Propeller Shaft	537631
BMW	Z4 Roadster (G29)	sDrive 20 i (120 kw)	2018.11-	Front	Engine B46 B20 B, B48 B20 B	Joint,Propeller Shaft	533422
BMW	Z4 Roadster (G29)	sDrive 20 i (145 kw)	2018.11-	Front	Engine B46 B20 B, B48 B20 B	Joint,Propeller Shaft	533422
BMW	Z4 Roadster (G29)	sDrive 30 i (190 kw)	2018.11-	Front	Engine B46 B20 B, B48 B20 B	Joint,Propeller Shaft	533422
MERCEDES BENZ	C-CLASS (A205)	AMG C 43 (270 kw)	2016.10-2018.05	Front and Rear	AWD Engine M 276.823	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS (A205)	C 180 (115 kw)	2016.06-	Front and Rear	Engine M 274.910	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS (A205)	C 200 (135 kw)	2016.06-2018.05	Front and Rear	AWD Engine M 274.920	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS (A205)	C 200 (135 kw)	2016.06-2018.05	Front and Rear	Engine M 274.920	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS (A205)	C 220 d (120 kw)	2016.06-2018.05	Front	Engine OM 651.921	Joint,Propeller Shaft	537630
MERCEDES BENZ	C-CLASS (A205)	C 220 d (125 kw)	2016.06-2018.05	Front and Rear	AWD Engine OM 651.921	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS (A205)	C 220 d (125 kw)	2016.06-2018.05	Front	Engine OM 651.921	Joint,Propeller Shaft	537630
MERCEDES BENZ	C-CLASS (A205)	C 220 d (143 kw)	2018.04-	Front	Engine OM 654.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	C-CLASS (A205)	C 300 (180 kw)	2016.06-2018.05	Front	Engine M 274.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	C-CLASS (A205)	C 400 (245 kw)	2016.06-	Front and Rear	AWD Engine M 276.823	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS (W203)	C 240 (125 kw)	2002.07-2007.02	Front And Rear	AWD Engine M 112.916	Joint,Propeller Shaft	533884
MERCEDES BENZ	C-CLASS (W203)	C 320 (160 kw)	2002.07-2007.02	Front And Rear	AWD Engine M 112.953	Joint,Propeller Shaft	533884
MERCEDES BENZ	C-CLASS (W203)	C 320 CDI (165 kw)	2005.01-2007.02	Front And Rear	Engine OM 642.910	Joint,Propeller Shaft	533884
MERCEDES BENZ	C-CLASS (W204)	C 250 CDI (150 kw)	2008.08-2014.01	Front And Rear	Engine OM 651.911	Joint,Propeller Shaft	533884
MERCEDES BENZ	C-CLASS (W204)	C 320 CDI (165 kw)	2007.01-2014.01	Front And Rear	Engine OM 642.960	Joint,Propeller Shaft	533884
MERCEDES BENZ	C-CLASS (W204)	C 350 CDI (165 kw)	2009.07-2014.01	Front And Rear	Engine OM 642.960	Joint,Propeller Shaft	533884
MERCEDES BENZ	C-CLASS (W204)	C 350 CDI (170 kw)	2009.10-2014.01	Front And Rear	Engine OM 642.830	Joint,Propeller Shaft	533884
MERCEDES BENZ	C-CLASS (W204)	C 350 CDI (195 kw)	2011.06-2014.01	Front And Rear	Engine OM 642.834	Joint,Propeller Shaft	533884
MERCEDES BENZ	C-CLASS (W204)	C 63 AMG (336 kw)	2008.02-2014.01	Front And Rear	Engine M 156.985	Joint,Propeller Shaft	533884
MERCEDES BENZ	C-CLASS (W204)	C 63 AMG (358 kw)	2008.02-2014.01	Front And Rear	Engine M 156.985	Joint,Propeller Shaft	533884
MERCEDES BENZ	C-CLASS (W205)	C 160 (95 kw)	2015.04-	Front and Rear	Engine M 274.910	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS (W205)	C 180 (115 kw)	2014.03-	Front and Rear	Engine M 274.910	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS (W205)	C 180 BlueTEC / d (85 kw)	2014.05-2018.05	Front and Rear	Engine OM 626.951	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS (W205)	C 180 Flex (115 kw)	2014.03-	Front and Rear	Engine M 274.910	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS (W205)	C 200 (135 kw)	2013.12-2018.08	Front and Rear	Engine M 274.920	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS (W205)	C 200 (135 kw)	2015.04-2018.08	Front and Rear	AWD Engine M 274.920	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS (W205)	C 200 BlueTEC / d (100 kw)	2014.05-2018.05	Front and Rear	Engine OM 626.951	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS (W205)	C 200 d (100 kw)	2015.10-2018.05	Front	Engine OM 651.921	Joint,Propeller Shaft	537630
MERCEDES BENZ	C-CLASS (W205)	C 220 BlueTEC / d (120 kw)	2014.03-2016.05	Front	Engine OM 651.921	Joint,Propeller Shaft	537630
MERCEDES BENZ	C-CLASS (W205)	C 220 BlueTEC / d (125 kw)	2014.02-2018.05	Front	Engine OM 651.921	Joint,Propeller Shaft	537630
MERCEDES BENZ	C-CLASS (W205)	C 220 d (125 kw)	2015.04-2018.05	Front and Rear	AWD Engine OM 651.921	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS (W205)	C 220 d (143 kw)	2018.05-	Front	Engine OM 654.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	C-CLASS (W205)	C 250 BlueTEC / d (150 kw)	2014.02-2018.05	Front and Rear	AWD Engine OM 651.921	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS (W205)	C 300 (180 kw)	2013.12-2018.08	Front and Rear	AWD Engine M 274.920	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS (W205)	C 300 (180 kw)	2015.09-2018.08	Front	Engine M 274.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	C-CLASS (W205)	C 400 (245 kw)	2014.10-	Front and Rear	AWD Engine M 276.823	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS (W205)	C 450 AMG (270 kw)	2015.04-2018.05	Front and Rear	AWD Engine M 276.823	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS (W205)	C 450 AMG (270 kw)	2015.04-2018.05	Front	AWD Engine M 276.823	Joint,Propeller Shaft	537630
MERCEDES BENZ	C-CLASS Coupe (C204)	C 200 CGI (135 kw)	2011.06-	Front	Engine M 271.860	Joint,Propeller Shaft	537630
MERCEDES BENZ	C-CLASS Coupe (C205)	AMG C 43 (270 kw)	2016.04-2018.05	Front and Rear	AWD Engine M 276.823	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS Coupe (C205)	C 180 (115 kw)	2015.10-	Front and Rear	Engine M 274.910	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS Coupe (C205)	C 200 (135 kw)	2015.10-2018.05	Front and Rear	Engine M 274.920	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS Coupe (C205)	C 200 (135 kw)	2016.04-2018.05	Front and Rear	AWD Engine M 274.920	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS Coupe (C205)	C 220 d (125 kw)	2016.04-2018.05	Front and Rear	AWD Engine OM 651.921	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS Coupe (C205)	C 220 d (143 kw)	2018.04-	Front	Engine OM 654.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	C-CLASS Coupe (C205)	C 250 d (150 kw)	2016.04-2018.05	Front and Rear	AWD Engine OM 651.921	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS Coupe (C205)	C 400 (245 kw)	2016.04-	Front and Rear	AWD Engine M 276.823	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS T-Model (S203)	C 240 (125 kw)	2002.07-2007.08	Front And Rear	AWD Engine M 112.916	Joint,Propeller Shaft	533884
MERCEDES BENZ	C-CLASS T-Model (S203)	C 320 CDI (165 kw)	2005.06-2007.08	Front And Rear	Engine OM 642.910	Joint,Propeller Shaft	533884
MERCEDES BENZ	C-CLASS T-Model (S204)	C 250 CDI (150 kw)	2009.01-2014.08	Front And Rear	Engine OM 651.911	Joint,Propeller Shaft	533884
MERCEDES BENZ	C-CLASS T-Model (S204)	C 320 CDI (165 kw)	2007.08-2014.08	Front And Rear	Engine OM 642.960	Joint,Propeller Shaft	533884
MERCEDES BENZ	C-CLASS T-Model (S204)	C 350 CDI (165 kw)	2007.08-2014.08	Front And Rear	Engine OM 642.830	Joint,Propeller Shaft	533884

MANUFACTURER	MODEL	DISPLACEMENT	YEAR	REMARK	FITTING POSITION	PRODUCT	GSP NO.
MERCEDES BENZ	C-CLASS T-Model (S204)	C 350 CDI (170 kw)	2009.10-2014.08	Front And Rear	Engine OM 642.830	Joint,Propeller Shaft	533884
MERCEDES BENZ	C-CLASS T-Model (S204)	C 350 CDI (195 kw)	2011.06-2014.08	Front And Rear	Engine OM 642.834	Joint,Propeller Shaft	533884
MERCEDES BENZ	C-CLASS T-Model (S204)	C 63 AMG (336 kw)	2008.02-2014.08	Front And Rear	Engine M 156.985	Joint,Propeller Shaft	533884
MERCEDES BENZ	C-CLASS T-Model (S204)	C 63 AMG (358 kw)	2012.01-2014.08	Front And Rear	Engine M 156.985	Joint,Propeller Shaft	533884
MERCEDES BENZ	C-CLASS T-Model (S205)	AMG C 43 (270 kw)	2016.04-2018.05	Front and Rear	AWD Engine M 276.823	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS T-Model (S205)	C 160 (95 kw)	2015.04-	Front and Rear	Engine M 274.910	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS T-Model (S205)	C 180 (115 kw)	2014.09-	Front and Rear	Engine M 274.910	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS T-Model (S205)	C 180 BlueTEC / d (85 kw)	2014.09-2018.05	Front and Rear	Engine OM 626.951	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS T-Model (S205)	C 200 (135 kw)	2014.09-2018.05	Front and Rear	Engine M 274.920	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS T-Model (S205)	C 200 (135 kw)	2015.04-2018.05	Front and Rear	AWD Engine M 274.920	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS T-Model (S205)	C 200 BlueTEC / d (100 kw)	2014.09-2018.05	Front and Rear	Engine OM 626.951	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS T-Model (S205)	C 200 d (100 kw)	2015.10-2018.05	Front	Engine OM 651.921	Joint,Propeller Shaft	537630
MERCEDES BENZ	C-CLASS T-Model (S205)	C 220 BlueTEC / d (120 kw)	2014.09-2018.05	Front	Engine OM 651.921	Joint,Propeller Shaft	537630
MERCEDES BENZ	C-CLASS T-Model (S205)	C 220 BlueTEC / d (125 kw)	2014.09-2018.05	Front	Engine OM 651.921	Joint,Propeller Shaft	537630
MERCEDES BENZ	C-CLASS T-Model (S205)	C 220 d (125 kw)	2015.04-2018.05	Front and Rear	AWD Engine OM 651.921	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS T-Model (S205)	C 220 d (143 kw)	2018.04-	Front	Engine OM 654.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	C-CLASS T-Model (S205)	C 250 BlueTEC / d (150 kw)	2014.10-2018.05	Front and Rear	AWD Engine OM 651.921	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS T-Model (S205)	C 300 (180 kw)	2015.09-2018.05	Front	Engine M 274.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	C-CLASS T-Model (S205)	C 400 (245 kw)	2014.10-	Front and Rear	AWD Engine M 276.823	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS T-Model (S205)	C 450 AMG (270 kw)	2015.04-2018.05	Front and Rear	AWD Engine M 276.823	Joint,Propeller Shaft	537627
MERCEDES BENZ	C-CLASS T-Model (S205)	C 450 AMG (270 kw)	2015.04-2018.05	Front	AWD Engine M 276.823	Joint,Propeller Shaft	537630
MERCEDES BENZ	CLK (A209)	CLK 320 CDI (165 kw)	2005.03-2010.03	Front And Rear	Engine OM 642.910	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLK (A209)	CLK 500 (285 kw)	2006.06-2010.03	Front And Rear	Engine M 273.967	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLK (A209)	CLK 63 AMG (354 kw)	2006.04-2010.03	Front And Rear	Engine M 156.982	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLK (C209)	320 CDI (165 kw)	2005.01-2009.05	Front And Rear	Engine OM 642.910	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLK (C209)	500 (285 kw)	2006.06-2009.05	Front And Rear	Engine M 273.965	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLK (C209)	63 AMG (354 kw)	2006.04-2009.05	Front And Rear	Engine M 156.982	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLS (C218)	CLS 220 BlueTEC / d (120 kw)	2014.05-2017.12	Front	Engine OM 651.924	Joint,Propeller Shaft	537630
MERCEDES BENZ	CLS (C218)	CLS 220 BlueTEC / d (125 kw)	2014.05-2017.12	Front	Engine OM 651.924	Joint,Propeller Shaft	537630
MERCEDES BENZ	CLS (C218)	CLS 220 BlueTEC / d (130 kw)	2014.05-2017.12	Front	Engine OM 651.924	Joint,Propeller Shaft	537630
MERCEDES BENZ	CLS (C218)	CLS 250 CDI / BlueTEC / d (150 kw)	2011.04-2017.12	Front And Rear	Engine OM 651.924	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLS (C218)	CLS 350 BlueTEC / d (185 kw)	2013.02-2017.12	Front And Rear	Engine OM 642.852, OM 642.853	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLS (C218)	CLS 350 CDI / d (195 kw)	2011.01-2014.08	Front And Rear	Engine OM 642.852, OM 642.853	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLS (C218)	CLS 500 (300 kw)	2011.09-2017.12	Front	AWD Engine M 278.922	Joint,Propeller Shaft	537630
MERCEDES BENZ	CLS (C218)	CLS 63 AMG (386 kw)	2011.01-2017.12	Front And Rear	Engine M 157.980, M 157.981	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLS (C218)	CLS 63 AMG (410 kw)	2011.01-2017.12	Front And Rear	Engine M 157.980, M 157.981	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLS (C218)	CLS 63 AMG (410 kw)	2013.05-2017.12	Front And Rear	AWD Engine M 157.981	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLS (C219)	CLS 320 CDI (155 kw)	2005.01-2010.12	Front And Rear	Engine OM 642.920	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLS (C219)	CLS 320 CDI (165 kw)	2005.01-2010.12	Front And Rear	Engine OM 642.920	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLS (C219)	CLS 350 CDI (165 kw)	2009.04-2010.12	Front And Rear	Engine OM 642.920	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLS (C219)	CLS 500 (285 kw)	2006.04-2010.12	Front And Rear	Engine M 273.960	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLS (C219)	CLS 55 AMG (350 kw)	2005.01-2010.12	Front And Rear	Engine M 113.990	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLS (C219)	CLS 63 AMG (378 kw)	2006.04-2010.12	Front And Rear	Engine M 156.983	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLS (C257)	CLS 350 d (183 kw)	2017.12-	Front	AWD Engine OM 656.929	Joint,Propeller Shaft	537630
MERCEDES BENZ	CLS (C257)	CLS 350 EQ Boost (220 kw)	2018.08-	Front and Rear	AWD Engine M 264.920	Joint,Propeller Shaft	537627
MERCEDES BENZ	CLS (C257)	CLS 400 d (250 kw)	2017.12-	Front	AWD Engine OM 656.929	Joint,Propeller Shaft	537630
MERCEDES BENZ	CLS (C257)	CLS 450 EQ Boost (270 kw)	2017.12-	Front and Rear	AWD Engine M 256.930	Joint,Propeller Shaft	537627
MERCEDES BENZ	CLS (C257)	CLS 450 EQ Boost (270 kw)	2017.12-	Front	AWD Engine M 256.930	Joint,Propeller Shaft	537630
MERCEDES BENZ	CLS Shooting Brake (X218)	CLS 250 CDI / BlueTEC / d (150 kw)	2012.10-2017.12	Front And Rear	Engine OM 651.924	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLS Shooting Brake (X218)	CLS 350 CDI / d (195 kw)	2012.10-2014.08	Front And Rear	Engine OM 642.852, OM 642.853	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLS Shooting Brake (X218)	CLS 500 (300 kw)	2012.10-2017.12	Front And Rear	Engine M 278.922	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLS Shooting Brake (X218)	CLS 63 AMG (386 kw)	2012.10-2017.12	Front And Rear	Engine M 157.981	Joint,Propeller Shaft	533884
MERCEDES BENZ	CLS Shooting Brake (X218)	CLS 63 AMG (410 kw)	2013.05-2017.12	Front And Rear	AWD Engine M 157.981	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (A207)	E 220 CDI (120 kw)	2010.02-2016.12	Front	Engine OM 651.911	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (A207)	E 220 CDI / BlueTEC / d (125 kw)	2010.01-2016.12	Front	Engine OM 651.911	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (A207)	E 250 CDI / BlueTEC / d (150 kw)	2010.01-2016.12	Front And Rear	Engine OM 651.911	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (A207)	E 350 BlueTEC (185 kw)	2013.06-2016.12	Front And Rear	Engine OM 642.838	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (A207)	E 350 CDI (170 kw)	2010.01-2011.12	Front And Rear	Engine OM 642.836	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (A207)	E 350 CDI (195 kw)	2011.04-2013.12	Front And Rear	Engine OM 642.838	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (A207)	E 500 (285 kw)	2010.01-2011.12	Front And Rear	Engine M 273.966	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (A207)	E 500 (300 kw)	2011.09-2016.12	Front And Rear	Engine M 278.922	Joint,Propeller Shaft	533884

MANUFACTURER	MODEL	DISPLACEMENT	YEAR	REMARK	FITTING POSITION	PRODUCT	GSP NO.
MERCEDES BENZ	E-CLASS (A238)	E 220 d (120 kw)	2017.06-	Front	Engine OM 654.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (A238)	E 220 d (143 kw)	2017.06-	Front	Engine OM 654.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (A238)	E 220 d (143 kw)	2017.10-	Front	AWD Engine OM 654.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (A238)	E 300 (180 kw)	2017.06-	Front	Engine M 274.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (A238)	E 350 d (190 kw)	2017.06-	Front	AWD Engine OM 642.873	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (A238)	E 350 EQ Boost (220 kw)	2017.10-	Front	Engine M 264.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (A238)	E 400 (245 kw)	2017.06-	Front	AWD Engine M 276.823	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (VF211)	E 280 CDI (140 kw)	2005.08-2009.07	Front And Rear	Engine OM 642.920	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W211)	E 280 CDI (130 kw)	2004.05-2008.12	Front And Rear	Engine OM 648.961	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W211)	E 280 CDI (140 kw)	2005.03-2008.12	Front And Rear	AWD Engine OM 642.921	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W211)	E 280 CDI (140 kw)	2005.03-2008.12	Front And Rear	Engine OM 642.920	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W211)	E 300 BlueTEC (155 kw)	2007.09-2008.12	Front And Rear	Engine OM 642.920	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W211)	E 320 CDI (150 kw)	2002.11-2008.12	Front And Rear	Engine OM 648.961	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W211)	E 320 CDI (165 kw)	2005.03-2008.12	Front And Rear	AWD Engine OM 642.910, OM 642.921	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W211)	E 320 CDI (165 kw)	2005.03-2008.12	Front And Rear	Engine OM 642.920	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W211)	E 400 CDI (191 kw)	2003.02-2008.12	Front And Rear	Engine OM 628.961	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W211)	E 420 CDI (231 kw)	2006.01-2008.12	Front And Rear	Engine OM 629.910	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W211)	E 500 (285 kw)	2006.04-2008.12	Front And Rear	AWD Engine M 273.962	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W211)	E 500 (285 kw)	2006.04-2008.12	Front And Rear	Engine M 273.960	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W211)	E 55 AMG Kompressor (350 kw)	2002.10-2008.12	Front And Rear	Engine M 113.990	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W211)	E 63 AMG (378 kw)	2006.03-2008.12	Front And Rear	Engine M 156.983	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W212)	E 200 CDI / BlueTEC (100 kw)	2009.01-2015.12	Front	Engine OM 651.925	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (W212)	E 220 BlueTEC (125 kw)	2015.01-2015.12	Front	AWD Engine OM 651.924	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (W212)	E 220 BlueTEC (130 kw)	2014.05-2015.12	Front	Engine OM 651.924	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (W212)	E 220 CDI (120 kw)	2009.01-2015.12	Front	Engine OM 651.924	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (W212)	E 220 CDI / BlueTEC (125 kw)	2009.01-2016.12	Front	Engine OM 651.924	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (W212)	E 250 CDI / BlueTEC (150 kw)	2009.01-2016.12	Front And Rear	Engine OM 651.924	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W212)	E 300 CDI (150 kw)	2009.12-2010.12	Front And Rear	Engine OM 642.850	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W212)	E 300 CDI / BlueTEC (170 kw)	2011.03-2015.12	Front And Rear	Engine OM 642.850, OM 642.852	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W212)	E 350 BlueTEC (155 kw)	2009.01-2015.12	Front And Rear	Engine OM 642.850	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W212)	E 350 BlueTEC (185 kw)	2013.01-2015.12	Front And Rear	AWD Engine OM 642.858	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W212)	E 350 BlueTEC (185 kw)	2013.01-2015.12	Front And Rear	Engine OM 642.852	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W212)	E 350 CDI (170 kw)	2009.01-2015.12	Front And Rear	Engine OM 642.850	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W212)	E 350 CDI (195 kw)	2011.03-2015.12	Front And Rear	AWD Engine OM 642.858	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W212)	E 350 CDI (195 kw)	2011.03-2015.12	Front And Rear	Engine OM 642.852	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W212)	E 500 (285 kw)	2009.01-2011.12	Front And Rear	Engine M 273.971	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W212)	E 500 (300 kw)	2011.09-2015.12	Front And Rear	Engine M 278.922	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W212)	E 63 AMG (386 kw)	2009.12-2015.12	Front And Rear	Engine M 156.985	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W212)	E 63 AMG (386 kw)	2011.02-2016.12	Front And Rear	Engine M 157.980, M 157.981	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W212)	E 63 AMG (410 kw)	2011.02-2016.12	Front And Rear	Engine M 157.981	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W212)	E 63 AMG (410 kw)	2013.01-2016.12	Front And Rear	AWD Engine M 157.981	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS (W213)	AMG E 43 (295 kw)	2016.07-	Front	AWD Engine M 276.823	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (W213)	E 200 (135 kw)	2016.01-	Front and Rear	Engine M 274.920	Joint,Propeller Shaft	537627
MERCEDES BENZ	E-CLASS (W213)	E 200 (135 kw)	2016.07-	Front and Rear	AWD Engine M 274.920	Joint,Propeller Shaft	537627
MERCEDES BENZ	E-CLASS (W213)	E 200 d (110 kw)	2016.07-	Front	Engine OM 654.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (W213)	E 220 d (120 kw)	2016.01-	Front	Engine OM 654.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (W213)	E 220 d (120 kw)	2016.10-	Front	AWD Engine OM 654.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (W213)	E 220 d (143 kw)	2016.01-	Front	Engine OM 654.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (W213)	E 220 d (143 kw)	2016.10-	Front and Rear	AWD Engine OM 654.920	Joint,Propeller Shaft	537627
MERCEDES BENZ	E-CLASS (W213)	E 220 d (143 kw)	2016.10-	Front	AWD Engine OM 654.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (W213)	E 300 (180 kw)	2016.07-	Front	Engine M 274.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (W213)	E 300 (180 kw)	2016.09-	Front and Rear	AWD Engine M 274.920	Joint,Propeller Shaft	537627
MERCEDES BENZ	E-CLASS (W213)	E 300 d (180 kw)	2017.12-	Front	Engine OM 654.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (W213)	E 350 d (190 kw)	2017.06-2018.05	Front	AWD Engine OM 642.873	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (W213)	E 400 (245 kw)	2016.06-	Front	AWD Engine M 276.823	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS (W213)	E 400 (245 kw)	2016.07-	Front and Rear	AWD Engine M 276.853	Joint,Propeller Shaft	537627
MERCEDES BENZ	E-CLASS (W213)	E 400 (245 kw)	2016.07-	Front	AWD Engine M 276.853	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS All-Terrain (S213)	E 220 d (143 kw)	2017.01-	Front and Rear	AWD Engine OM 654.920	Joint,Propeller Shaft	537627
MERCEDES BENZ	E-CLASS All-Terrain (S213)	E 350 d (190 kw)	2017.06-	Front	AWD Engine OM 642.873	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS Coupe (C207)	E 220 BlueTEC (130 kw)	2014.05-2016.12	Front	Engine OM 651.911	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS Coupe (C207)	E 220 CDI / d (125 kw)	2010.01-2016.12	Front	Engine OM 651.911	Joint,Propeller Shaft	537630

MANUFACTURER	MODEL	DISPLACEMENT	YEAR	REMARK	FITTING POSITION	PRODUCT	GSP NO.
MERCEDES BENZ	E-CLASS Coupe (C207)	E 250 CDI / BlueTEC / d (150 kw)	2009.01-2016.12	Front And Rear	Engine OM 651.911	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS Coupe (C207)	E 350 BlueTEC (185 kw)	2013.06-2016.12	Front And Rear	Engine OM 642.838	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS Coupe (C207)	E 350 CDI (170 kw)	2009.01-2011.06	Front And Rear	Engine OM 642.836	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS Coupe (C207)	E 350 CDI (195 kw)	2011.06-2013.06	Front And Rear	Engine OM 642.838	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS Coupe (C207)	E 500 (285 kw)	2009.01-2016.12	Front And Rear	Engine M 273.966	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS Coupe (C207)	E 500 (300 kw)	2011.09-2016.12	Front And Rear	Engine M 278.922	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS Coupe (C238)	E 200 (135 kw)	2016.12-	Front and Rear	Engine M 274.920	Joint,Propeller Shaft	537627
MERCEDES BENZ	E-CLASS Coupe (C238)	E 220 d (120 kw)	2016.12-	Front	-	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS Coupe (C238)	E 220 d (143 kw)	2016.12-	Front	Engine OM 654.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS Coupe (C238)	E 220 d (143 kw)	2017.03-	Front and Rear	AWD Engine OM 654.920	Joint,Propeller Shaft	537627
MERCEDES BENZ	E-CLASS Coupe (C238)	E 220 d (143 kw)	2017.03-	Front	AWD Engine OM 654.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS Coupe (C238)	E 300 (180 kw)	2016.12-	Front	Engine M 274.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS Coupe (C238)	E 350 d (190 kw)	2017.06-	Front	AWD Engine OM 642.873	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS Coupe (C238)	E 350 EQ Boost (220 kw)	2017.10-	Front	Engine M 264.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS Coupe (C238)	E 400 (245 kw)	2016.12-	Front and Rear	AWD Engine M 276.823	Joint,Propeller Shaft	537627
MERCEDES BENZ	E-CLASS Coupe (C238)	E 400 (245 kw)	2016.12-	Front	AWD Engine M 276.823	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS T-Model (S211)	E 280 T CDI (130 kw)	2004.05-2009.07	Front And Rear	Engine OM 648.961	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S211)	E 280 T CDI (140 kw)	2005.03-2009.07	Front And Rear	AWD Engine OM 642.921	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S211)	E 280 T CDI (140 kw)	2005.03-2009.07	Front And Rear	Engine OM 642.920	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S211)	E 320 T CDI (150 kw)	2003.03-2009.07	Front And Rear	Engine OM 648.961	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S211)	E 320 T CDI (165 kw)	2005.03-2009.07	Front And Rear	AWD Engine OM 642.921	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S211)	E 320 T CDI (165 kw)	2005.03-2009.07	Front And Rear	Engine OM 642.920	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S211)	E 500 T (285 kw)	2006.04-2009.07	Front And Rear	AWD Engine M 273.962	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S211)	E 500 T (285 kw)	2006.04-2009.07	Front And Rear	Engine M 273.960	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S211)	E 55 T AMG Kompressor (350 kw)	2003.07-2009.07	Front And Rear	Engine M 113.990	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S211)	E 63 AMG (378 kw)	2006.03-2009.07	Front And Rear	Engine M 156.983	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S212)	E 200 CDI / BlueTEC (100 kw)	2009.11-2016.12	Front	Engine OM 651.925	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS T-Model (S212)	E 220 BlueTEC (125 kw)	2014.12-2016.12	Front	AWD Engine OM 651.924	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS T-Model (S212)	E 220 BlueTEC (130 kw)	2015.05-2016.12	Front	Engine OM 651.924	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS T-Model (S212)	E 220 CDI (120 kw)	2009.08-2014.08	Front	Engine OM 651.924	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS T-Model (S212)	E 220 CDI / BlueTEC (125 kw)	2009.11-2016.12	Front	Engine OM 651.924	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS T-Model (S212)	E 250 CDI / BlueTEC (150 kw)	2009.11-2016.12	Front And Rear	Engine OM 651.924	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S212)	E 300 CDI / BlueTEC (170 kw)	2009.11-2016.12	Front And Rear	Engine OM 642.850, OM 642.852	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S212)	E 350 BlueTEC (155 kw)	2009.11-2013.12	Front And Rear	Engine OM 642.850	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S212)	E 350 BlueTEC (185 kw)	2012.11-2016.12	Front And Rear	AWD Engine OM 642.858	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S212)	E 350 BlueTEC (185 kw)	2012.11-2016.12	Front And Rear	Engine OM 642.852	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S212)	E 350 CDI (170 kw)	2009.11-2011.12	Front And Rear	AWD Engine OM 642.856	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S212)	E 350 CDI (170 kw)	2009.11-2011.12	Front And Rear	Engine OM 642.850	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S212)	E 350 CDI (195 kw)	2011.07-2013.12	Front And Rear	AWD Engine OM 642.858	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S212)	E 350 CDI (195 kw)	2011.07-2013.12	Front And Rear	Engine OM 642.852	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S212)	E 500 (285 kw)	2009.11-2011.12	Front And Rear	Engine M 273.971	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S212)	E 500 (300 kw)	2011.09-2016.12	Front And Rear	Engine M 278.922	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S212)	E 63 AMG (386 kw)	2009.08-2011.12	Front And Rear	Engine M 156.985	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S212)	E 63 AMG (386 kw)	2011.02-2016.12	Front And Rear	Engine M 157.981	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S212)	E 63 AMG (410 kw)	2011.02-2016.12	Front And Rear	Engine M 157.981	Joint,Propeller Shaft	533884
MERCEDES BENZ	E-CLASS T-Model (S213)	AMG E 43 (295 kw)	2016.10-	Front	AWD Engine M 276.823	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS T-Model (S213)	E 200 (135 kw)	2016.07-	Front and Rear	Engine M 274.920	Joint,Propeller Shaft	537627
MERCEDES BENZ	E-CLASS T-Model (S213)	E 200 (135 kw)	2017.01-	Front and Rear	AWD Engine M 274.920	Joint,Propeller Shaft	537627
MERCEDES BENZ	E-CLASS T-Model (S213)	E 200 d (110 kw)	2016.10-	Front	Engine OM 654.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS T-Model (S213)	E 220 d (120 kw)	2016.07-	Front	Engine OM 654.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS T-Model (S213)	E 220 d (143 kw)	2016.07-	Front	Engine OM 654.920	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS T-Model (S213)	E 220 d (143 kw)	2017.01-	Front and Rear	AWD Engine OM 654.920	Joint,Propeller Shaft	537627
MERCEDES BENZ	E-CLASS T-Model (S213)	E 350 d (190 kw)	2017.06-	Front	AWD Engine OM 642.873	Joint,Propeller Shaft	537630
MERCEDES BENZ	E-CLASS T-Model (S213)	E 400 (245 kw)	2016.10-	Front and Rear	AWD Engine M 276.853	Joint,Propeller Shaft	537627
MERCEDES BENZ	E-CLASS T-Model (S213)	E 400 (245 kw)	2016.10-	Front	AWD Engine M 276.853	Joint,Propeller Shaft	537630
MERCEDES BENZ	GLC (X253)	250 d (150 kw)	2015.06-2019.04	Front	AWD Engine OM 651.921	Joint,Propeller Shaft	537630
MERCEDES BENZ	GLC (X253)	AMG 43 (270 kw)	2016.04-2019.08	Front and Rear	AWD Engine M 276.823	Joint,Propeller Shaft	537627
MERCEDES BENZ	GLC Coupe (C253)	250 d (150 kw)	2016.06-2019.04	Front	AWD Engine OM 651.921	Joint,Propeller Shaft	537630
MERCEDES BENZ	GLC Coupe (C253)	AMG 43 (270 kw)	2016.10-2019.08	Front and Rear	AWD Engine M 276.823	Joint,Propeller Shaft	537627
MERCEDES BENZ	GL-CLASS (X166)	GL 400 (245 kw)	2013.08-2015.10	Front	AWD Engine M 276.821	Joint,Propeller Shaft	537630
MERCEDES BENZ	GL-CLASS (X166)	GL 450 (270 kw)	2012.07-2015.10	Front	AWD Engine M 278.928	Joint,Propeller Shaft	537630

MANUFACTURER	MODEL	DISPLACEMENT	YEAR	REMARK	FITTING POSITION	PRODUCT	GSP NO.
MERCEDES BENZ	GL-CLASS (X166)	GL 500 (310 kw)	2015.04-2015.12	Front	AWD Engine M 278.912	Joint,Propeller Shaft	537630
MERCEDES BENZ	GL-CLASS (X166)	GL 500 (320 kw)	2012.07-2015.10	Front	AWD Engine M 278.928	Joint,Propeller Shaft	537630
MERCEDES BENZ	GLE (W166)	500 (320 kw)	2015.04-2018.10	Front	AWD Engine M 278.928	Joint,Propeller Shaft	537630
MERCEDES BENZ	GLE (W166)	500 (335 kw)	2015.10-2018.10	Front	AWD Engine M 278.928	Joint,Propeller Shaft	537630
MERCEDES BENZ	GLE (W166)	AMG 43 (270 kw)	2016.05-2018.10	Front	AWD Engine M 276.821	Joint,Propeller Shaft	537630
MERCEDES BENZ	GLE (W166)	AMG 43 (287 kw)	2017.06-2018.10	Front	AWD Engine M 276.821	Joint,Propeller Shaft	537630
MERCEDES BENZ	GLE Coupe (C292)	320 (200 kw)	2015.09-2019.10	Front	AWD Engine M 276.821	Joint,Propeller Shaft	537630
MERCEDES BENZ	GLE Coupe (C292)	400 (245 kw)	2015.03-2019.10	Front and Rear	AWD Engine M 276.821, M 276.825	Joint,Propeller Shaft	537627
MERCEDES BENZ	GLE Coupe (C292)	400 (245 kw)	2015.03-2019.10	Front	AWD Engine M 276.821, M 276.825	Joint,Propeller Shaft	537630
MERCEDES BENZ	GLE Coupe (C292)	450 AMG (270 kw)	2015.03-2019.10	Front	AWD Engine M 276.821	Joint,Propeller Shaft	537630
MERCEDES BENZ	GLE Coupe (C292)	500 (310 kw)	2016.12-2019.10	Front	AWD Engine M 278.912	Joint,Propeller Shaft	537630
MERCEDES BENZ	GLE Coupe (C292)	500 (335 kw)	2015.10-2019.10	Front	AWD Engine M 278.928	Joint,Propeller Shaft	537630
MERCEDES BENZ	M-CLASS (W166)	ML 500 (300 kw)	2012.02-2015.02	Front	AWD Engine M 278.928	Joint,Propeller Shaft	537630
MERCEDES BENZ	S-CLASS (W220)	S 55 AMG Kompressor (368 kw)	2002.06-2005.08	Front And Rear	Engine M 113.991	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS (W220)	S 600 (368 kw)	2002.09-2005.08	Front And Rear	Engine M 275.950	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS (W220)	S 65 AMG (450 kw)	2004.03-2005.08	Front And Rear	Engine M 275.980	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS (W221)	S 320 CDI (155 kw)	2005.10-2013.12	Front And Rear	Engine OM 642.930	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS (W221)	S 320 CDI (173 kw)	2005.12-2009.06	Front And Rear	Engine OM 642.930	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS (W221)	S 350 BlueTec (190 kw)	2011.04-2013.12	Front And Rear	Engine OM 642.862	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS (W221)	S 350 CDI (155 kw)	2009.06-2013.12	Front And Rear	Engine OM 642.930	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS (W221)	S 350 CDI (173 kw)	2009.06-2013.12	Front And Rear	Engine OM 642.930	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS (W221)	S 420 CDI (235 kw)	2006.10-2009.12	Front And Rear	Engine OM 629.911	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS (W221)	S 450 CDI (235 kw)	2009.01-2013.12	Front And Rear	Engine OM 629.911	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS (W221)	S 500 (271 kw)	2011.05-2013.12	Front And Rear	Engine M 273.961	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS (W221)	S 500 (285 kw)	2005.10-2013.12	Front And Rear	Engine M 273.961	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS (W221)	S 500 CGI (320 kw)	2011.04-2013.12	Front And Rear	Engine M 278.932	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS (W221)	S 600 (380 kw)	2005.12-2013.12	Front And Rear	Engine M 275.953	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS (W221)	S 63 AMG (386 kw)	2006.10-2013.12	Front And Rear	Engine M 156.984	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS (W221)	S 65 AMG (450 kw)	2005.12-2013.12	Front And Rear	Engine M 275.982	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS (W221)	S 65 AMG (463 kw)	2010.10-2013.12	Front And Rear	Engine M 275.982	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS (W222, V222, X222)	S 320 (200 kw)	2014.05-	Front	Engine M 276.824	Joint,Propeller Shaft	537630
MERCEDES BENZ	S-CLASS (W222, V222, X222)	S 350 BlueTEC (185 kw)	2014.02-2017.05	Front	AWD Engine OM 642.867	Joint,Propeller Shaft	537630
MERCEDES BENZ	S-CLASS (W222, V222, X222)	S 350 BlueTEC / d (190 kw)	2014.02-2017.05	Front	AWD Engine OM 642.861, OM 642.867	Joint,Propeller Shaft	537630
MERCEDES BENZ	S-CLASS (W222, V222, X222)	S 350 d (210 kw)	2017.05-	Front	AWD Engine OM 656.929	Joint,Propeller Shaft	537630
MERCEDES BENZ	S-CLASS (W222, V222, X222)	S 350 L (230 kw)	2017.09-	Front	Engine M 276.824	Joint,Propeller Shaft	537630
MERCEDES BENZ	S-CLASS (W222, V222, X222)	S 400 (245 kw)	2014.11-2017.05	Front and Rear	AWD Engine M 276.824	Joint,Propeller Shaft	537627
MERCEDES BENZ	S-CLASS (W222, V222, X222)	S 400 d (250 kw)	2017.05-	Front	AWD Engine OM 656.929	Joint,Propeller Shaft	537630
MERCEDES BENZ	S-CLASS (W222, V222, X222)	S 400 Maybach (245 kw)	2015.01-2017.05	Front and Rear	AWD Engine M 276.824	Joint,Propeller Shaft	537627
MERCEDES BENZ	S-CLASS (W222, V222, X222)	S 500 (335 kw)	2013.05-2017.05	Front	AWD Engine M 278.929	Joint,Propeller Shaft	537630
MERCEDES BENZ	S-CLASS (W222, V222, X222)	S 500 Maybach (310 kw)	2015.09-2017.05	Front	AWD Engine M 278.910	Joint,Propeller Shaft	537630
MERCEDES BENZ	S-CLASS (W222, V222, X222)	S 500 Maybach (335 kw)	2015.04-2017.05	Front	AWD Engine M 278.929	Joint,Propeller Shaft	537630
MERCEDES BENZ	S-CLASS (W222, V222, X222)	S 560 (345 kw)	2017.05-	Front	AWD Engine M 176.980	Joint,Propeller Shaft	537630
MERCEDES BENZ	S-CLASS (W222, V222, X222)	S 560 Maybach (345 kw)	2017.07-	Front	AWD Engine M 176.980	Joint,Propeller Shaft	537630
MERCEDES BENZ	S-CLASS Coupe (C215)	CL 55 AMG Kompressor (368 kw)	2002.06-2006.03	Front And Rear	Engine M 113.991	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS Coupe (C215)	CL 600 (368 kw)	2002.09-2006.03	Front And Rear	Engine M 275.950	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS Coupe (C215)	CL 65 AMG (450 kw)	2003.09-2006.03	Front And Rear	Engine M 275.980	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS Coupe (C216)	CL 500 (285 kw)	2006.06-2013.12	Front And Rear	Engine M 273.961	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS Coupe (C216)	CL 600 (380 kw)	2006.05-2013.12	Front And Rear	Engine M 275.953	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS Coupe (C216)	CL 63 AMG (386 kw)	2006.10-2013.12	Front And Rear	Engine M 156.984	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS Coupe (C216)	CL 65 AMG (450 kw)	2006.10-2010.12	Front And Rear	Engine M 275.982	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS Coupe (C216)	CL 65 AMG (463 kw)	2011.02-2013.12	Front And Rear	Engine M 275.982	Joint,Propeller Shaft	533884
MERCEDES BENZ	S-CLASS Coupe (C217)	S 400 (270 kw)	2015.10-	Front and Rear	AWD Engine M 276.824	Joint,Propeller Shaft	537627
MERCEDES BENZ	S-CLASS Coupe (C217)	S 500 (310 kw)	2014.11-2017.10	Front	AWD Engine M 278.910	Joint,Propeller Shaft	537630
MERCEDES BENZ	S-CLASS Coupe (C217)	S 500 (335 kw)	2014.04-2017.10	Front	AWD Engine M 278.929	Joint,Propeller Shaft	537630
MERCEDES BENZ	S-CLASS Coupe (C217)	S 560 (345 kw)	2017.10-	Front	AWD Engine M 176.980	Joint,Propeller Shaft	537630
MERCEDES BENZ	SL (R230)	500 (285 kw)	2006.03-2012.01	Front And Rear	Engine M 273.965	Joint,Propeller Shaft	533884
MERCEDES BENZ	SL (R230)	55 AMG (380 kw)	2006.03-2012.01	Front And Rear	Engine M 113.995	Joint,Propeller Shaft	533884
MERCEDES BENZ	SL (R230)	55 AMG Kompressor (368 kw)	2002.06-2012.01	Front And Rear	Engine M 113.992	Joint,Propeller Shaft	533884
MERCEDES BENZ	SL (R230)	600 (368 kw)	2003.04-2012.01	Front And Rear	Engine M 275.951	Joint,Propeller Shaft	533884
MERCEDES BENZ	SL (R230)	600 (380 kw)	2006.03-2012.01	Front And Rear	Engine M 275.954	Joint,Propeller Shaft	533884
MERCEDES BENZ	SL (R230)	65 AMG (450 kw)	2004.03-2012.01	Front And Rear	Engine M 275.981	Joint,Propeller Shaft	533884

MANUFACTURER	MODEL	DISPLACEMENT	YEAR	REMARK	FITTING POSITION	PRODUCT	GSP NO.
MERCEDES BENZ	VITO/MIXTO (W639)	119 (140 kw)	2003.09-	Front And Rear	Engine M 112.951	Joint,Propeller Shaft	533884
MERCEDES BENZ	VITO/MIXTO (W639)	120 CDI (150 kw)	2006.07-	Front And Rear	Engine OM 642.990	Joint,Propeller Shaft	533884
MERCEDES BENZ	VITO/MIXTO (W639)	122 (160 kw)	2003.09-	Front And Rear	Engine M 112.951	Joint,Propeller Shaft	533884
MERCEDES BENZ	VITO/MIXTO (W639)	122 CDI (165 kw)	2010.09-	Front And Rear	Engine OM 642.890	Joint,Propeller Shaft	533884
MERCEDES BENZ	VITO/MIXTO (W639)	123 (165 kw)	2004.06-2008.07	Front And Rear	Engine M 112.976	Joint,Propeller Shaft	533884
MERCEDES BENZ	VITO/MIXTO (W639)	123 (170 kw)	2004.06-2008.07	Front And Rear	Engine M 112.976	Joint,Propeller Shaft	533884
MERCEDES BENZ	VITO/MIXTO (W639)	126 (190 kw)	2007.09-	Front And Rear	Engine M 272.978	Joint,Propeller Shaft	533884
SEAT	ALHAMBRA (710, 711)	2.0 TDI (103 kw)	2011.05-	Rear	AWD Engine CFFB	Joint,Propeller Shaft	533882
SEAT	ALHAMBRA (710, 711)	2.0 TDI (103 kw)	2011.05-	Front	AWD Engine CFFB	Joint,Propeller Shaft	537626
SEAT	ALHAMBRA (710, 711)	2.0 TDI (110 kw)	2015.05-	Rear	AWD Engine CUVVC, DFLA	Joint,Propeller Shaft	533882
SEAT	ALHAMBRA (710, 711)	2.0 TDI (110 kw)	2015.05-	Front	AWD Engine CUVVC, DFLA	Joint,Propeller Shaft	537626
SEAT	ALHAMBRA (710, 711)	2.0 TDI (135 kw)	2016.05-	Rear	AWD Engine DFMA	Joint,Propeller Shaft	533882
SEAT	ALHAMBRA (710, 711)	2.0 TDI (135 kw)	2016.05-	Front	AWD Engine DFMA	Joint,Propeller Shaft	537626
SEAT	ALTEA XL (5P5, 5P8)	1.9 TDI (77 kw)	2009.06-2010.12	Rear	AWD Engine BLS	Joint,Propeller Shaft	533882
SEAT	ALTEA XL (5P5, 5P8)	2.0 TDI (103 kw)	2007.06-	Rear	AWD Engine BMM	Joint,Propeller Shaft	533882
SEAT	ALTEA XL (5P5, 5P8)	2.0 TDI (103 kw)	2007.06-	Front	AWD Engine BMM	Joint,Propeller Shaft	537626
SEAT	ALTEA XL (5P5, 5P8)	2.0 TDI (125 kw)	2007.06-	Rear	AWD Engine BMN, CEGA, CFJA	Joint,Propeller Shaft	533882
SEAT	ALTEA XL (5P5, 5P8)	2.0 TDI (125 kw)	2007.06-	Front	AWD Engine BMN, CEGA, CFJA	Joint,Propeller Shaft	537626
SEAT	ALTEA XL (5P5, 5P8)	2.0 TDI 16V (103 kw)	2010.10-	Rear	AWD Engine CFHC	Joint,Propeller Shaft	533882
SEAT	ALTEA XL (5P5, 5P8)	2.0 TFSI (147 kw)	2007.06-2009.05	Rear	AWD Engine BWA	Joint,Propeller Shaft	533882
SEAT	ALTEA XL (5P5, 5P8)	2.0 TFSI (147 kw)	2007.06-2009.05	Front	AWD Engine BWA	Joint,Propeller Shaft	537626
SEAT	ALTEA XL (5P5, 5P8)	2.0 TFSI (155 kw)	2009.05-	Rear	AWD Engine CCZB	Joint,Propeller Shaft	533882
SEAT	ALTEA XL (5P5, 5P8)	2.0 TFSI (155 kw)	2009.05-	Front	AWD Engine CCZB	Joint,Propeller Shaft	537626
SEAT	LEON (1M1)	1.8 20V T 4 (132 kw)	1999.11-2006.06	Front	AWD Engine AJQ, ARY (03.00-)	Joint,Propeller Shaft	537626
SEAT	LEON (1M1)	1.9 TDI Syncro (110 kw)	2002.05-2006.06	Front	AWD Engine ARL	Joint,Propeller Shaft	537626
SEAT	LEON (1M1)	2.8 Cupra 4 (150 kw)	2001.02-2006.06	Front	AWD Engine AUE, BDE	Joint,Propeller Shaft	537626
SKODA	OCTAVIA I Combi (1U5)	1.9 TDI (74 kw)	2000.09-2006.01	Front	AWD Engine ATD	Joint,Propeller Shaft	537626
SKODA	OCTAVIA II Combi (125)	1.6 TDI (77 kw)	2009.06-2013.02	Rear	AWD Engine CAYC	Joint,Propeller Shaft	533882
SKODA	OCTAVIA II Combi (125)	1.8 TSI (112 kw)	2009.03-2013.02	Rear	AWD Engine CDAB	Joint,Propeller Shaft	533882
SKODA	OCTAVIA II Combi (125)	1.8 TSI (118 kw)	2008.11-2013.02	Rear	AWD Engine CDA A	Joint,Propeller Shaft	533882
SKODA	OCTAVIA II Combi (125)	1.9 TDI (77 kw)	2004.11-2010.12	Rear	AWD Engine BKC, BLS, BXE	Joint,Propeller Shaft	533882
SKODA	OCTAVIA II Combi (125)	1.9 TDI (77 kw)	2004.11-2010.12	Front	AWD Engine BKC, BLS, BXE	Joint,Propeller Shaft	537626
SKODA	OCTAVIA II Combi (125)	2.0 FSI (110 kw)	2004.11-2009.04	Rear	AWD Engine BLX, BLY, BVX	Joint,Propeller Shaft	533882
SKODA	OCTAVIA II Combi (125)	2.0 FSI (110 kw)	2004.11-2009.04	Front	AWD Engine BLX, BLY, BVX	Joint,Propeller Shaft	537626
SKODA	OCTAVIA II Combi (125)	2.0 TDI (103 kw)	2006.07-2010.05	Rear	AWD Engine BMM	Joint,Propeller Shaft	533882
SKODA	OCTAVIA II Combi (125)	2.0 TDI (103 kw)	2006.07-2010.05	Front	AWD Engine BMM	Joint,Propeller Shaft	537626
SKODA	OCTAVIA II Combi (125)	2.0 TDI (81 kw)	2011.05-2013.02	Rear	AWD Engine CFHF	Joint,Propeller Shaft	533882
SKODA	OCTAVIA II Combi (125)	2.0 TDI 16V (103 kw)	2010.05-2013.02	Rear	AWD Engine BKD, CFHC, CLCB	Joint,Propeller Shaft	533882
SKODA	SUPERB II (3T4)	1.8 TSI (112 kw)	2009.03-2015.05	Rear	AWD Engine CDAB	Joint,Propeller Shaft	533882
SKODA	SUPERB II (3T4)	1.8 TSI (118 kw)	2008.11-2015.05	Rear	AWD Engine CDA A	Joint,Propeller Shaft	533882
SKODA	SUPERB II (3T4)	2.0 TDI (125 kw)	2008.09-2015.05	Rear	AWD Engine CBBB, CFGB	Joint,Propeller Shaft	533882
SKODA	SUPERB II (3T4)	2.0 TDI 16V (103 kw)	2010.11-2015.05	Rear	AWD Engine CFFB	Joint,Propeller Shaft	533882
SKODA	SUPERB II (3T4)	3.6 FSI (191 kw)	2008.11-2015.05	Rear	AWD Engine CDVA	Joint,Propeller Shaft	533882
SKODA	SUPERB II (3T5)	1.8 TSI (112 kw)	2009.10-2015.05	Rear	AWD Engine CDAB	Joint,Propeller Shaft	533882
SKODA	SUPERB II (3T5)	1.8 TSI (118 kw)	2009.10-2015.05	Rear	AWD Engine CDA A	Joint,Propeller Shaft	533882
SKODA	SUPERB II (3T5)	2.0 TDI (125 kw)	2009.10-2015.05	Rear	AWD Engine CBBB, CFGB	Joint,Propeller Shaft	533882
SKODA	SUPERB II (3T5)	2.0 TDI 16V (103 kw)	2010.11-2015.05	Rear	AWD Engine CFFB	Joint,Propeller Shaft	533882
SKODA	SUPERB II (3T5)	3.6 V6 (191 kw)	2009.10-2015.05	Rear	AWD Engine CDVA	Joint,Propeller Shaft	533882
SKODA	YETI (5L)	1.4 TSI (110 kw)	2015.05-2017.12	Rear	AWD Engine CZDA	Joint,Propeller Shaft	533882
SKODA	YETI (5L)	1.8 TSI (112 kw)	2009.11-2017.12	Rear	AWD Engine CDAB	Joint,Propeller Shaft	533882
SKODA	YETI (5L)	1.8 TSI (118 kw)	2009.05-2017.12	Rear	AWD Engine CDA A	Joint,Propeller Shaft	533882
SKODA	YETI (5L)	2.0 TDI (103 kw)	2009.05-2017.12	Rear	AWD Engine CBDB, CFHC, CLCB	Joint,Propeller Shaft	533882
SKODA	YETI (5L)	2.0 TDI (110 kw)	2015.05-2017.12	Rear	AWD Engine CUUB, DFSB	Joint,Propeller Shaft	533882
SKODA	YETI (5L)	2.0 TDI (125 kw)	2009.11-2015.05	Rear	AWD Engine CEGA, CFJA	Joint,Propeller Shaft	533882
SKODA	YETI (5L)	2.0 TDI (81 kw)	2009.11-2017.12	Rear	AWD Engine CFHF, CUUA, DFSA	Joint,Propeller Shaft	533882
TOYOTA	ALLION I (_T24_)	1.8 (97 kW)	2001.06-2007.06	Front	AWD Engine 1ZZ-FE	Center Bearing Support	513043
TOYOTA	ALLION II (_T26_)	1.8 (96 kW)	2013.03-	Front	AWD Engine 2ZR-FAE	Center Bearing Support	513043
TOYOTA	ALLION II (_T26_)	1.8 (98 kW)	2007.07-2013.02	Front	AWD Engine 2ZR-FAE	Center Bearing Support	513043
TOYOTA	bB I (NCP3_)	1.5 (80 kW)	2000.03-2005.12	Rear	Engine 1NZ-FE	Center Bearing Support	537001
TOYOTA	CALDINA (_T24_)	2.0 (110 kW)	2002.09-2007.06	Front	AWD Engine 1AZ-FSE	Center Bearing Support	513043
TOYOTA	CALDINA (_T24_)	2.0 (114 kW)	2002.09-2007.06	Front	AWD Engine 1AZ-FSE	Center Bearing Support	513043

MANUFACTURER	MODEL	DISPLACEMENT	YEAR	REMARK	FITTING POSITION	PRODUCT	GSP NO.
TOYOTA	CALDINA (_T24_)	2.0 (191 kW)	2002.09-2007.06	Front	AWD Engine 3S-GTE	Center Bearing Support	513043
TOYOTA	COROLLA (_E14_)FIELDER	1.5 (77 kW)	2006.09-	Front	AWD Engine 1NZ-FE	Center Bearing Support	513043
TOYOTA	COROLLA (_E14_)FIELDER	1.5 (81 kW)	2006.09-	Front	Engine 1NZ-FE	Center Bearing Support	513043
TOYOTA	COROLLA (_E14_)FIELDER	1.8 (100 kW)	2006.09-	Front	Engine 2ZR-FE	Center Bearing Support	513043
TOYOTA	COROLLA (_E14_)FIELDER	1.8 (98 kW)	2006.09-2012.04	Front	AWD Engine 2ZR-FAE	Center Bearing Support	513043
TOYOTA	COROLLA (_E15_)	1.5 (77 kW)	2007.08-2012.05	Front	AWD Engine 1NZ-FE	Center Bearing Support	513043
TOYOTA	COROLLA (_E15_)	1.8 (98 kW)	2007.08-2012.05	Front	AWD Engine 2ZR-FAE, 2ZR-FE	Center Bearing Support	513043
TOYOTA	ISIS (_M1_)	1.8 VVTi (98 kW)	2007.04-2014.08	Front	AWD Engine 2ZR-FAE	Center Bearing Support	513043
TOYOTA	ISIS (_M1_)	2.0 VVTi (114 kW)	2004.07-2014.08	Front	AWD Engine 1AZ-FSE	Center Bearing Support	513043
TOYOTA	IST (NCP6_)XA	1.5 VVTi (80 kW)	2002.05-2007.06	Rear	AWD Engine 1NZ-FE	Center Bearing Support	537001
TOYOTA	PLATZ (NCP1_, SCP1_)	1.3 (63 kW)	1999.08-2005.08	Rear	AWD Engine 2NZ-FE	Center Bearing Support	537001
TOYOTA	PLATZ (NCP1_, SCP1_)	1.3 (63 kW)	1999.08-2005.08	Rear	Engine 2NZ-FE	Center Bearing Support	537001
TOYOTA	PORTE (_NNP1_)	1.5 (77 kW)	2004.07-2012.07	Rear	AWD Engine 1NZ-FE	Center Bearing Support	537001
TOYOTA	PREMIO (_T24_)	1.8 (92 kW)	2001.12-2007.06	Front	AWD Engine 1ZZ-FE	Center Bearing Support	513043
TOYOTA	PREMIO (_T24_)	1.8 (97 kW)	2001.12-2007.04	Front	AWD Engine 1ZZ-FE	Center Bearing Support	513043
TOYOTA	PREMIO (_T26_)	1.8 (92 kW)	2008.01-	Front	AWD Engine 2ZR-FAE, 2ZR-FE	Center Bearing Support	513043
TOYOTA	PREMIO (_T26_)	1.8 (96 kW)	2013.03-	Front	AWD Engine 2ZR-FAE	Center Bearing Support	513043
TOYOTA	PREMIO (_T26_)	1.8 (98 kW)	2007.07-2013.02	Front	AWD Engine 2ZR-FAE	Center Bearing Support	513043
TOYOTA	PROBOX (_P16_)	1.5 VVTi (76 kW)	2014.09-	Rear	AWD Engine 1NZ-FE	Center Bearing Support	537001
TOYOTA	PROBOX/SUCCEED (_P5_)	1.5 VVTi (77 kW)	2002.07-2014.08	Rear	AWD Engine 1NZ-FE	Center Bearing Support	537001
TOYOTA	PROBOX/SUCCEED (_P5_)	1.5 VVTi (80 kW)	2002.07-2014.08	Rear	AWD Engine 1NZ-FE	Center Bearing Support	537001
TOYOTA	RAUM (NCZ2_)	1.5 (77 kW)	2003.05-	Rear	AWD Engine 1NZ-FE	Center Bearing Support	537001
TOYOTA	RAUM (NCZ2_)	1.5 (80 kW)	2003.05-	Rear	Engine 1NZ-FE	Center Bearing Support	537001
TOYOTA	SUPRA (DB_)	2.0 (145 kw)	2019.06-	Front	Engine B48L	Joint,Propeller Shaft	533422
TOYOTA	SUPRA (DB_)	2.0 (190 kw)	2019.06-	Front	Engine B48H	Joint,Propeller Shaft	533422
TOYOTA	WILL CYPHA (NCP7_)	1.5 VVTi (78 kW)	2001.05-2005.07	Rear	AWD Engine 1NZ-FE	Center Bearing Support	537001
TOYOTA	WISH (_E1_)	1.8 Hi (92 kW)	2003.04-2009.03	Front	AWD Engine 1ZZ-FE	Center Bearing Support	513043
TOYOTA	WISH (_E1_)	1.8 Hi (97 kW)	2003.04-2009.03	Front	Engine 1ZZ-FE	Center Bearing Support	513043
TOYOTA	WISH (_E2_)	1.8 (96 kW)	2012.04-	Front	AWD Engine 2ZR-FAE	Center Bearing Support	513043
TOYOTA	WISH (_E2_)	1.8 (98 kW)	2009.04-2012.03	Front	AWD Engine 2ZR-FAE	Center Bearing Support	513043
TOYOTA	YARIS (_L1_)YARIS/VITZ/ZIECHO/ECHO	1.3 (65 kW)	1999.09-2005.01	Rear	AWD Engine 2NZ-FE	Center Bearing Support	537001
VW	BORA (1J2)	1.8 (92 kw)	1999.02-2005.05	Front	AWD Engine AGN	Joint,Propeller Shaft	537626
VW	BORA (1J2)	1.9 TDI (110 kw)	2000.05-2005.05	Front	AWD Engine ARL	Joint,Propeller Shaft	537626
VW	BORA (1J2)	1.9 TDI (74 kw)	2000.09-2005.05	Front	AWD Engine ATD	Joint,Propeller Shaft	537626
VW	BORA (1J2)	1.9 TDI (96 kw)	2000.11-2005.05	Front	AWD Engine ASZ	Joint,Propeller Shaft	537626
VW	BORA (1J2)	2.0 (85 kw)	2000.04-2005.05	Front	AWD Engine AZH (02.01-), AZJ	Joint,Propeller Shaft	537626
VW	BORA (1J2)	2.3 V5 (125 kw)	2000.10-2005.05	Front	AWD Engine AQN	Joint,Propeller Shaft	537626
VW	BORA (1J2)	2.8 V6 (150 kw)	1999.03-2005.05	Front	AWD Engine ADP (05.99-05.00), AUE (05.00-), BDE	Joint,Propeller Shaft	537626
VW	BORA Variant (1J6)	1.8 (92 kw)	1999.05-2005.05	Front	AWD Engine AGN (05.99-)	Joint,Propeller Shaft	537626
VW	BORA Variant (1J6)	1.9 TDI (110 kw)	2001.05-2005.05	Front	AWD Engine ARL	Joint,Propeller Shaft	537626
VW	BORA Variant (1J6)	1.9 TDI (74 kw)	2000.09-2005.05	Front	AWD Engine ATD (09.00-)	Joint,Propeller Shaft	537626
VW	BORA Variant (1J6)	1.9 TDI (96 kw)	2000.11-2005.05	Front	AWD Engine ASZ	Joint,Propeller Shaft	537626
VW	BORA Variant (1J6)	2.0 (85 kw)	2000.04-2005.05	Front	AWD Engine AZH (04.00-), AZJ	Joint,Propeller Shaft	537626
VW	BORA Variant (1J6)	2.3 V5 (125 kw)	2000.10-2005.05	Front	AWD Engine AQN	Joint,Propeller Shaft	537626
VW	BORA Variant (1J6)	2.8 V6 (150 kw)	1999.05-2005.05	Front	AWD Engine ADP (05.99-05.00), AUE (05.00-), BDE	Joint,Propeller Shaft	537626
VW	CADDY III (2KA, 2KH, 2CA, 2CH)	1.9 TDI (77 kw)	2008.11-2010.08	Front	AWD Engine BLS	Joint,Propeller Shaft	537626
VW	CADDY III (2KA, 2KH, 2CA, 2CH)	2.0 TDI (62 kw)	2010.12-2015.05	Front	AWD Engine CFHE	Joint,Propeller Shaft	537626
VW	CADDY III (2KA, 2KH, 2CA, 2CH)	2.0 TDI (81 kw)	2010.08-2015.05	Front	AWD Engine CFHF	Joint,Propeller Shaft	537626
VW	CADDY III (2KA, 2KH, 2CA, 2CH)	2.0 TDI 16V (103 kw)	2010.11-2015.05	Front	AWD Engine CFHC	Joint,Propeller Shaft	537626
VW	CADDY III (2KB, 2KJ, 2CB, 2CJ)	1.9 TDI (77 kw)	2008.05-2010.08	Front	AWD Engine BLS	Joint,Propeller Shaft	537626
VW	CADDY III (2KB, 2KJ, 2CB, 2CJ)	2.0 TDI (81 kw)	2010.08-2015.05	Front	AWD Engine CFHF	Joint,Propeller Shaft	537626
VW	CADDY III (2KB, 2KJ, 2CB, 2CJ)	2.0 TDI 16V (103 kw)	2010.11-2015.05	Front	AWD Engine CFHC	Joint,Propeller Shaft	537626
VW	CC (358)	2.0 TDI (103 kw)	2011.11-2016.12	Rear	AWD Engine CFFB	Joint,Propeller Shaft	533882
VW	CC (358)	2.0 TDI (125 kw)	2011.11-2013.01	Rear	AWD Engine CFGB	Joint,Propeller Shaft	533882
VW	CC (358)	2.0 TDI (130 kw)	2012.12-2016.12	Rear	AWD Engine CFGC	Joint,Propeller Shaft	533882
VW	GOLF IV (1J1)	1.8 (92 kw)	1998.05-2005.06	Front	AWD Engine AGN	Joint,Propeller Shaft	537626
VW	GOLF IV (1J1)	1.9 TDI (110 kw)	2000.02-2005.06	Front	AWD Engine ARL	Joint,Propeller Shaft	537626
VW	GOLF IV (1J1)	1.9 TDI (74 kw)	2000.09-2005.06	Front	AWD Engine ATD	Joint,Propeller Shaft	537626
VW	GOLF IV (1J1)	1.9 TDI (96 kw)	2000.11-2005.06	Front	AWD Engine ASZ	Joint,Propeller Shaft	537626
VW	GOLF IV (1J1)	2.0 (85 kw)	2000.10-2005.06	Front	AWD Engine AZH, AZJ	Joint,Propeller Shaft	537626
VW	GOLF IV (1J1)	2.3 V5 (125 kw)	2000.10-2005.06	Front	AWD Engine AQN	Joint,Propeller Shaft	537626

MANUFACTURER	MODEL	DISPLACEMENT	YEAR	REMARK	FITTING POSITION	PRODUCT	GSP NO.
VW	GOLF IV (1J1)	2.8 VR6 (150 kw)	1999.03-2005.06	Front	AWD Engine AQP, AUE, BDE	Joint,Propeller Shaft	537626
VW	GOLF IV (1J1)	3.2 R32 (177 kw)	2002.09-2005.06	Front	AWD Engine BFH, BJS, BML	Joint,Propeller Shaft	537626
VW	GOLF IV Variant (1J5)	1.8 (92 kw)	1999.05-2006.06	Front	AWD Engine AGN	Joint,Propeller Shaft	537626
VW	GOLF IV Variant (1J5)	1.9 TDI (74 kw)	2000.09-2006.06	Front	AWD Engine ATD	Joint,Propeller Shaft	537626
VW	GOLF IV Variant (1J5)	1.9 TDI (96 kw)	2000.11-2006.06	Front	AWD Engine ASZ	Joint,Propeller Shaft	537626
VW	GOLF IV Variant (1J5)	2.0 (85 kw)	2000.10-2006.06	Front	AWD Engine AZH, AZJ	Joint,Propeller Shaft	537626
VW	GOLF IV Variant (1J5)	2.3 V5 (110 kw)	1999.05-2006.06	Front	AWD Engine AGZ (05.99-)	Joint,Propeller Shaft	537626
VW	GOLF IV Variant (1J5)	2.3 V5 (125 kw)	2000.10-2006.06	Front	AWD Engine AQN (10.00-)	Joint,Propeller Shaft	537626
VW	GOLF IV Variant (1J5)	2.8 V6 (150 kw)	1999.05-2006.06	Front	AWD Engine AQP, AUE, BDE	Joint,Propeller Shaft	537626
VW	GOLF V (1K1)	1.9 TDI (77 kw)	2004.08-2008.11	Rear	AWD Engine BKC, BLS, BXE	Joint,Propeller Shaft	533882
VW	GOLF V (1K1)	1.9 TDI (77 kw)	2004.08-2008.11	Front	AWD Engine BKC, BLS, BXE	Joint,Propeller Shaft	537626
VW	GOLF V (1K1)	2.0 FSI (110 kw)	2004.08-2008.11	Rear	AWD Engine BLX, BVX	Joint,Propeller Shaft	533882
VW	GOLF V (1K1)	2.0 FSI (110 kw)	2004.08-2008.11	Front	AWD Engine BLX, BVX	Joint,Propeller Shaft	537626
VW	GOLF V (1K1)	2.0 TDI (103 kw)	2004.08-2008.11	Rear	AWD Engine BMM	Joint,Propeller Shaft	533882
VW	GOLF V (1K1)	2.0 TDI (103 kw)	2004.08-2008.11	Front	AWD Engine BMM	Joint,Propeller Shaft	537626
VW	GOLF V (1K1)	2.0 TDI 16V (103 kw)	2004.08-2008.11	Rear	AWD Engine BKD	Joint,Propeller Shaft	533882
VW	GOLF V (1K1)	2.0 TDI 16V (103 kw)	2004.08-2008.11	Front	AWD Engine BKD	Joint,Propeller Shaft	537626
VW	GOLF V (1K1)	3.2 R32 (184 kw)	2005.11-2008.11	Front	AWD Engine BUB, CBRA	Joint,Propeller Shaft	537626
VW	GOLF V Variant (1K5)	1.9 TDI (77 kw)	2008.01-2009.07	Front	AWD Engine BLS	Joint,Propeller Shaft	537626
VW	GOLF VI (5K1)	2.0 R (188 kw)	2009.11-2013.11	Rear	AWD Engine CDLC, CRZA	Joint,Propeller Shaft	533882
VW	GOLF VI (5K1)	2.0 R (195 kw)	2009.11-2011.05	Rear	AWD Engine CDLA	Joint,Propeller Shaft	533882
VW	GOLF VI (5K1)	2.0 R (199 kw)	2009.11-2012.11	Rear	AWD Engine CDLF	Joint,Propeller Shaft	533882
VW	GOLF VI (5K1)	2.0 R (199 kw)	2009.11-2012.11	Front	AWD Engine CDLF	Joint,Propeller Shaft	537626
VW	GOLF VI (5K1)	2.0 TDI (103 kw)	2009.05-2012.11	Rear	AWD Engine CBAB, CFFB	Joint,Propeller Shaft	533882
VW	GOLF VI (5K1)	2.0 TDI (103 kw)	2009.05-2012.11	Front	AWD Engine CBAB, CFFB	Joint,Propeller Shaft	537626
VW	GOLF VI Van (5K1_)	2.0 TSi R (199 kw)	2009.11-2012.11	Rear	AWD Engine CDLF	Joint,Propeller Shaft	533882
VW	GOLF VI Variant (AJ5)	1.6 TDI (77 kw)	2009.07-2013.07	Rear	AWD Engine CAYC	Joint,Propeller Shaft	533882
VW	GOLF VI Variant (AJ5)	1.6 TDI (77 kw)	2009.07-2013.07	Front	AWD Engine CAYC	Joint,Propeller Shaft	537626
VW	PASSAT (362)	2.0 TDI (103 kw)	2010.08-2014.12	Rear	AWD Engine CFFB	Joint,Propeller Shaft	533882
VW	PASSAT (362)	2.0 TDI (103 kw)	2010.08-2014.12	Front	AWD Engine CFFB	Joint,Propeller Shaft	537626
VW	PASSAT (362)	2.0 TDI (125 kw)	2010.08-2013.01	Rear	AWD Engine CFGB	Joint,Propeller Shaft	533882
VW	PASSAT (362)	2.0 TDI (125 kw)	2010.08-2013.01	Front	AWD Engine CFGB	Joint,Propeller Shaft	537626
VW	PASSAT (362)	2.0 TDI (130 kw)	2013.01-2014.12	Rear	AWD Engine CFGC	Joint,Propeller Shaft	533882
VW	PASSAT (365)	3.6 FSi (220 kw)	2011.01-2014.12	Front	AWD Engine BWS	Joint,Propeller Shaft	537626
VW	PASSAT (3C2)/PASSAT/Magotan	2.0 FSI (110 kw)	2005.09-2010.07	Rear	AWD Engine BLX, BLY, BVX	Joint,Propeller Shaft	533882
VW	PASSAT (3C2)/PASSAT/Magotan	2.0 FSI (110 kw)	2005.09-2010.07	Front	AWD Engine BLX, BLY, BVX	Joint,Propeller Shaft	537626
VW	PASSAT (3C2)/PASSAT/Magotan	2.0 TDI (103 kw)	2005.03-2009.05	Rear	AWD Engine BMP	Joint,Propeller Shaft	533882
VW	PASSAT (3C2)/PASSAT/Magotan	2.0 TDI (103 kw)	2005.03-2009.05	Front	AWD Engine BMP	Joint,Propeller Shaft	537626
VW	PASSAT (3C2)/PASSAT/Magotan	2.0 TDI (125 kw)	2009.05-2010.07	Rear	AWD Engine CBBB	Joint,Propeller Shaft	533882
VW	PASSAT (3C2)/PASSAT/Magotan	2.0 TDI (125 kw)	2009.05-2010.07	Front	AWD Engine CBBB	Joint,Propeller Shaft	537626
VW	PASSAT (3C2)/PASSAT/Magotan	2.0 TDI 16V (103 kw)	2005.03-2010.08	Rear	AWD Engine BKP, CBAB	Joint,Propeller Shaft	533882
VW	PASSAT (3C2)/PASSAT/Magotan	2.0 TDI 16V (103 kw)	2005.03-2010.08	Front	AWD Engine BKP, CBAB	Joint,Propeller Shaft	537626
VW	PASSAT (3C2)/PASSAT/Magotan	3.2 FSI (184 kw)	2005.11-2010.07	Front	AWD Engine AXZ	Joint,Propeller Shaft	537626
VW	PASSAT (3C2)/PASSAT/Magotan	3.6 R36 (220 kw)	2007.04-2010.07	Front	AWD Engine BWS	Joint,Propeller Shaft	537626
VW	PASSAT ALLTRACK (365)	2.0 TDI (103 kw)	2012.01-2014.12	Rear	AWD Engine CFFB	Joint,Propeller Shaft	533882
VW	PASSAT ALLTRACK (365)	2.0 TDI (125 kw)	2012.01-2014.12	Rear	AWD Engine CFGB	Joint,Propeller Shaft	533882
VW	PASSAT ALLTRACK (365)	2.0 TDI (130 kw)	2013.01-2014.12	Rear	AWD Engine CFGC	Joint,Propeller Shaft	533882
VW	PASSAT ALLTRACK (365)	2.0 TSI (155 kw)	2012.01-2014.12	Rear	AWD Engine CCZB	Joint,Propeller Shaft	533882
VW	PASSAT CC (357)	2.0 TDI (103 kw)	2009.08-2012.01	Rear	AWD Engine CBAB, CFFB	Joint,Propeller Shaft	533882
VW	PASSAT CC (357)	2.0 TDI (103 kw)	2009.08-2012.01	Front	AWD Engine CBAB, CFFB	Joint,Propeller Shaft	537626
VW	PASSAT CC (357)	2.0 TDI (125 kw)	2009.11-2012.01	Rear	AWD Engine CBBB, CFGB	Joint,Propeller Shaft	533882
VW	PASSAT CC (357)	2.0 TDI (125 kw)	2009.11-2012.01	Front	AWD Engine CBBB, CFGB	Joint,Propeller Shaft	537626
VW	PASSAT CC (357)	3.6 FSI (206 kw)	2008.06-2012.01	Front	AWD Engine BLV, CNNA	Joint,Propeller Shaft	537626
VW	PASSAT CC (357)	3.6 FSI (220 kw)	2008.02-2011.12	Front	AWD Engine BWS	Joint,Propeller Shaft	537626
VW	PASSAT Variant (365)/MAGOTAN	2.0 TDI (103 kw)	2010.08-2014.12	Rear	AWD Engine CFFB	Joint,Propeller Shaft	533882
VW	PASSAT Variant (365)/MAGOTAN	2.0 TDI (103 kw)	2010.08-2014.12	Front	AWD Engine CFFB	Joint,Propeller Shaft	537626
VW	PASSAT Variant (365)/MAGOTAN	2.0 TDI (125 kw)	2010.08-2013.01	Rear	AWD Engine CFGB	Joint,Propeller Shaft	533882
VW	PASSAT Variant (365)/MAGOTAN	2.0 TDI (125 kw)	2010.08-2013.01	Front	AWD Engine CFGB	Joint,Propeller Shaft	537626
VW	PASSAT Variant (365)/MAGOTAN	2.0 TDI (130 kw)	2013.01-2014.12	Rear	AWD Engine CFGC	Joint,Propeller Shaft	533882
VW	PASSAT Variant (365)/MAGOTAN	3.6 FSI (220 kw)	2011.01-2014.12	Front	AWD Engine BWS	Joint,Propeller Shaft	537626
VW	PASSAT Variant (3C5)	2.0 FSI (110 kw)	2005.09-2010.11	Rear	AWD Engine BLX, BLY, BVX	Joint,Propeller Shaft	533882



MANUFACTURER	MODEL	DISPLACEMENT	YEAR	REMARK	FITTING POSITION	PRODUCT	GSP NO.
VW	PASSAT Variant (3C5)	2.0 FSI (110 kw)	2005.09-2010.11	Front	AWD Engine BLX, BLY, BVX	Joint,Propeller Shaft	537626
VW	PASSAT Variant (3C5)	2.0 TDI (103 kw)	2005.08-2009.05	Rear	AWD Engine BMP	Joint,Propeller Shaft	533882
VW	PASSAT Variant (3C5)	2.0 TDI (103 kw)	2005.08-2009.05	Front	AWD Engine BMP	Joint,Propeller Shaft	537626
VW	PASSAT Variant (3C5)	2.0 TDI (125 kw)	2009.05-2010.11	Rear	AWD Engine CBBB	Joint,Propeller Shaft	533882
VW	PASSAT Variant (3C5)	2.0 TDI (125 kw)	2009.05-2010.11	Front	AWD Engine CBBB	Joint,Propeller Shaft	537626
VW	PASSAT Variant (3C5)	2.0 TDI 16V (103 kw)	2005.08-2010.11	Rear	AWD Engine BKP, CBAB	Joint,Propeller Shaft	533882
VW	PASSAT Variant (3C5)	2.0 TDI 16V (103 kw)	2005.08-2010.11	Front	AWD Engine BKP, CBAB	Joint,Propeller Shaft	537626
VW	PASSAT Variant (3C5)	3.2 FSI (184 kw)	2005.11-2010.11	Front	AWD Engine AXZ	Joint,Propeller Shaft	537626
VW	PASSAT Variant (3C5)	3.6 R36 (220 kw)	2007.04-2010.11	Front	AWD Engine BWS	Joint,Propeller Shaft	537626
VW	SHARAN (7N1, 7N2)	2.0 TDI (103 kw)	2011.05-	Rear	AWD Engine CFFB	Joint,Propeller Shaft	533882
VW	SHARAN (7N1, 7N2)	2.0 TDI (103 kw)	2011.05-	Front	AWD Engine CFFB	Joint,Propeller Shaft	537626
VW	SHARAN (7N1, 7N2)	2.0 TDI (110 kw)	2015.05-	Rear	AWD Engine CUVC, DFLA, DLTA	Joint,Propeller Shaft	533882
VW	SHARAN (7N1, 7N2)	2.0 TDI (135 kw)	2016.05-	Rear	AWD Engine DFMA	Joint,Propeller Shaft	533882
VW	TIGUAN (5N_)	1.4 TSI (110 kw)	2007.09-2018.07	Rear	AWD Engine BWK, CAVA, CTHA	Joint,Propeller Shaft	533882
VW	TIGUAN (5N_)	1.4 TSI (118 kw)	2011.05-2018.07	Rear	AWD Engine CAVD, CTHD	Joint,Propeller Shaft	533882
VW	TIGUAN (5N_)	2.0 TDI (100 kw)	2007.11-2018.07	Rear	AWD Engine CBAA, CFFA	Joint,Propeller Shaft	533882
VW	TIGUAN (5N_)	2.0 TDI (103 kw)	2007.09-2018.07	Rear	AWD Engine CBAB, CFFB, CLJA	Joint,Propeller Shaft	533882
VW	TIGUAN (5N_)	2.0 TDI (110 kw)	2015.05-2018.07	Rear	AWD Engine CUVC	Joint,Propeller Shaft	533882
VW	TIGUAN (5N_)	2.0 TDI (120 kw)	2008.02-2009.08	Rear	AWD Engine CBBA	Joint,Propeller Shaft	533882
VW	TIGUAN (5N_)	2.0 TDI (125 kw)	2007.09-2018.07	Rear	AWD Engine CBBB, CFGB	Joint,Propeller Shaft	533882
VW	TIGUAN (5N_)	2.0 TDI (130 kw)	2012.11-2018.07	Rear	AWD Engine CFGC	Joint,Propeller Shaft	533882
VW	TIGUAN (5N_)	2.0 TDI (135 kw)	2015.05-2018.07	Rear	AWD Engine CUWA	Joint,Propeller Shaft	533882
VW	TIGUAN (5N_)	2.0 TFSI (125 kw)	2007.09-2018.07	Rear	AWD Engine CAWA, CCZC	Joint,Propeller Shaft	533882
VW	TIGUAN (5N_)	2.0 TFSI (147 kw)	2007.09-2018.07	Rear	AWD Engine CAWB, CCTA, CCZA	Joint,Propeller Shaft	533882
VW	TIGUAN (5N_)	2.0 TSI (132 kw)	2011.05-2018.07	Rear	AWD Engine CCZD	Joint,Propeller Shaft	533882
VW	TIGUAN (5N_)	2.0 TSI (155 kw)	2011.05-2018.07	Rear	AWD Engine CCZB	Joint,Propeller Shaft	533882

Drive Line Part

Photo.....

<p>513043</p> <p>TOYOTA Ref.No. 3723039035</p> 	<p>533422</p> <p>BMW Ref.No. 26117522027</p> 	<p>533882</p> <p>AUDI Ref.No. 1K0521307 1K0521307A</p> 	<p>533884</p> <p>MERCEDES BENZ Ref.No. 0004110600 0004110700 2094100215 2154100015 2214100415 2214110115 2404100215 2404100415</p> 
--	--	---	--

<p>537001</p> <p>TOYOTA Ref.No. 3723010030 3723010031 3723059025</p> 	<p>537625</p> <p>BMW Ref.No. 26117610372 26112226842</p> 	<p>537626</p> <p>AUDI Ref.No. 1J0521127 1J0521127A</p> 	<p>537627</p> <p>MERCEDES BENZ Ref.No. 2054110000 A2054110000</p> 
--	--	---	---

<p>537630</p> <p>MERCEDES BENZ Ref.No. 2054110100</p> 	<p>537631</p> <p>BMW Ref.No. 26111229360</p> 		
---	--	--	--

GSP Group Headquarter

No.1 Gaoxiang Road, High-tech Industrial Zone
Ouhai District,Wenzhou, China
Tel:+86-577-86293118 / 86293268
Fax:+86-577-86293313
E-mail:internationalsales@gsp.cn
www.gsp.cn

GSP Nanjing Co., Ltd

No.59 Shuanghu Road
Gaochun District, Nanjing, China
Tel: +86-25-56838033
E-mail:internationalsales@gsp.cn
www.gsp.cn

GSP Europe GmbH

Leyboldstraße 10
D 50354 Hürth
Tel:+49-2233-80-58-155
Fax:+49-2233-80-58-156
E-mail:info@gsp-europe.com
www.gsp-europe.com

GSP North America (West Coast)

15315 Marquardt Ave.
Santa Fe Springs, CA 90670
Tel: +1-562-926-3525
Fax: +1-562-376-8550
Email: tech@gsp-na.com / info@gsp-na.com
www.gspnorthamerica.com

GSP North America (East Coast)

2725 New Cut Road
Spartanburg SC 29303
Tel:+1-864-578-6900 / +1-800-243-7225
Fax:+1-864-578-6978
E-mail:tech@gsp-na.com / info@gsp-na.com
www.gspnorthamerica.com

GSP North America (Latin America)

3150 SW 38th Ave. Suite 1312
Coral Gables, FL 33146
Tel: +1-305-446-7702 / +1-305-446-7703
Fax: +1-305-446-7701
Email: info@gsplatinamerica.com
www.gsplatinamerica.com

